

ISO 105-B04:2024-03 (E)

Textiles - Tests for colour fastness - Part B04: Colour fastness to artificial weathering: Xenon arc fading lamp test

Contents	Page
Foreword.....	iv
Introduction.....	v
1 Scope.....	1
2 Normative references.....	1
3 Terms and definitions.....	1
4 Principle.....	2
5 Materials.....	2
5.1 Blue wool references.....	2
5.2 Glass case for blue wool references.....	2
5.3 Specimen mounting cards.....	2
5.4 Specimen covers.....	2
5.5 Specimen holders.....	2
5.6 Grey scale for assessing change in colour.....	2
6 Apparatus.....	3
6.1 Laboratory light source.....	3
6.1.1 General.....	3
6.1.2 Spectral irradiance.....	3
6.2 Test chamber.....	4
6.3 Radiometer.....	5
6.4 Temperature sensors.....	5
6.4.1 General.....	5
6.4.2 Chamber air temperature thermometer.....	5
6.4.3 Black-standard thermometer (BST) and black-panel thermometer (BPT).....	5
7 Exposure conditions.....	5
7.1 General.....	5
7.2 Exposure of test specimens.....	5
7.3 Exposure of colour fastness references.....	6
8 Test specimens.....	6
9 Procedure.....	6
9.1 General.....	6
9.2 Exposure methods.....	7
9.2.1 General.....	7
9.2.2 Method 1.....	7
9.2.3 Method 2.....	7
9.2.4 Method 3.....	8
9.3 Drying.....	8
9.4 Mounting for assessment.....	8
10 Assessment of colour fastness to weathering.....	8
11 Test report.....	9
Annex A (informative) General information on colour fastness to light.....	10
Annex B (informative) Radiometer for controlling exposure duration.....	12
Bibliography.....	13