

ISO 17973:2024-07 (E)

Surface chemical analysis - Medium-resolution Auger electron spectrometers - Calibration of energy scales for elemental analysis

Contents		Page
Foreword		iv
Introduction		v
1 Scope		1
2 Normative references		1
3 Terms and definitions		1
4 Symbols and abbreviated terms		1
5 Outline of method		2
6 Energy scale calibration procedures		3
6.1 Obtaining reference samples.....		3
6.2 Mounting samples.....		3
6.3 Cleaning samples.....		3
6.4 Choosing spectrometer settings for energy calibration.....		5
6.5 Operating the instrument.....		5
6.6 Measurement of reference peaks.....		6
6.7 Determining measured kinetic energies of reference peaks.....		7
6.8 Determining correction of instrument kinetic energy scale.....		8
6.9 Next calibration.....		9
Bibliography		11