

# ISO 17973:2024-07 (E)

## Surface chemical analysis - Medium-resolution Auger electron spectrometers - Calibration of energy scales for elemental analysis

---

<b>Contents</b>		<b>Page</b>
<b>Foreword</b> .....		<b>iv</b>
<b>Introduction</b> .....		<b>v</b>
<b>1 Scope</b> .....		<b>1</b>
<b>2 Normative references</b> .....		<b>1</b>
<b>3 Terms and definitions</b> .....		<b>1</b>
<b>4 Symbols and abbreviated terms</b> .....		<b>1</b>
<b>5 Outline of method</b> .....		<b>2</b>
<b>6 Energy scale calibration procedures</b> .....		<b>3</b>
6.1 Obtaining reference samples.....		3
6.2 Mounting samples.....		3
6.3 Cleaning samples.....		3
6.4 Choosing spectrometer settings for energy calibration.....		5
6.5 Operating the instrument.....		5
6.6 Measurement of reference peaks.....		6
6.7 Determining measured kinetic energies of reference peaks.....		7
6.8 Determining correction of instrument kinetic energy scale.....		8
6.9 Next calibration.....		9
<b>Bibliography</b> .....		<b>11</b>