

# DIN EN ISO 4259-4:2025-09 (E)

## Petroleum and related products - Precision of measurement methods and results - Part 4: Use of statistical control charts to validate 'in-statistical-control' status for the execution of a standard test method in a single laboratory (ISO 4259-4:2021, Corrected version 2023-10)

---

| <b>Contents</b>   | <b>Page</b> |
|---|-------------|
| <b>Foreword</b> .....   | <b>iv</b>   |
| <b>Introduction</b> .....   | <b>v</b>    |
| <b>1 Scope</b> .....  | <b>1</b>    |
| <b>2 Normative references</b> .....   | <b>1</b>    |
| <b>3 Terms, definitions, symbols and abbreviated terms</b> .....                              | <b>1</b>    |
| 3.1 Specific terms and definitions.....   | 2           |
| 3.2 Symbols and abbreviated terms.....  | 2           |
| <b>4 Statistical control in the execution of a standard test method by a laboratory</b> ..... | <b>3</b>    |
| 4.1 General.....  | 3           |
| 4.2 Control chart description.....  | 4           |
| 4.2.1 General.....  | 4           |
| 4.2.2 I- and MR-charts.....   | 4           |
| 4.2.3 I-chart sensitivity enhancement strategy.....   | 4           |
| 4.2.4 In-statistical-control conditions.....  | 5           |
| 4.3 Control chart work process.....   | 5           |
| 4.3.1 General.....  | 5           |
| 4.3.2 Stage 1 of control chart work process.....  | 5           |
| 4.3.3 Stage 2 of control chart work process.....  | 9           |
| 4.4 QC material batch change transition.....  | 11          |
| 4.4.1 General.....  | 11          |
| 4.4.2 Procedure 1, concurrent testing.....  | 12          |
| 4.4.3 Procedure 2, Q-chart.....   | 12          |
| 4.4.4 Procedure 3, dynamically updated I-chart with EWMA.....                                 | 12          |
| <b>5 Guidance for insufficient variation or non-normal data</b> .....                         | <b>13</b>   |
| 5.1 General requirement.....  | 13          |
| 5.2 How to deal with insufficient variation or non-normal data.....                           | 13          |
| 5.2.1 Insufficient variation.....   | 13          |
| 5.2.2 Non-normal data.....  | 14          |
| <b>Annex A (informative) Details of the control chart work process</b> .....                  | <b>15</b>   |
| <b>Annex B (normative) Check procedures</b> .....   | <b>34</b>   |
| <b>Bibliography</b> .....   | <b>36</b>   |