

ISO 9348:2026-05 (E)

Textiles - Determination of the anti-contamination propensity of fabrics to particulate matter - Digital measurement method

Contents

Page

- Foreword..... iv
- Introduction..... v
- 1 Scope..... 1
- 2 Normative references..... 1
- 3 Terms and definitions..... 1
- 4 Principle..... 2
- 5 Apparatus and material..... 2
- 6 Conditioning and testing atmosphere..... 4
 - 6.1 Test particle conditioning..... 4
 - 6.2 Test atmosphere and conditioning..... 4
- 7 Preparation of test..... 4
 - 7.1 Test specimens..... 4
 - 7.2 Test specimen canister..... 4
- 8 Procedure..... 5
- 9 Assessment..... 5
 - 9.1 Image acquisition method..... 5
 - 9.2 Image acquisition procedure..... 5
 - 9.3 Image analysis..... 5
 - 9.4 Calculation and expression of results..... 6
- 10 Test report..... 6
- Annex A (informative) Test particle..... 7
- Bibliography..... 8