

ISO 6892-2:2026-08 (E)

Metallic materials - Tensile testing - Part 2: Method of test at elevated temperature

Contents	Page
Foreword	iv
Introduction	v
1 Scope	1
2 Normative references	1
3 Terms and definitions	1
4 Symbols	2
5 Principle	2
6 Test piece	3
7 Determination of original cross-sectional area (S_0)	3
8 Marking the original gauge length (L_0)	3
9 Apparatus	3
10 Test conditions	4
10.1 Setting the force zero point	4
10.2 Gripping of the test piece, fixing of the extensometer and heating of the test piece, not necessarily in the following sequence	5
10.2.1 Method of gripping	5
10.2.2 Fixing of the extensometer and establishing the gauge length	5
10.2.3 Heating of the test piece	6
10.3 Testing rate based on strain rate control (Method A)	6
10.3.1 General	6
10.3.2 Strain rate for the determination of the upper yield strength (R_{eH}) or proof strength properties (R_p and, if required, R_t)	6
10.3.3 Strain rate for the determination of the lower yield strength (R_{eL}) and percentage yield point extension (A_e), if required	6
10.3.4 Strain rate for the determination of the tensile strength (R_m), percentage elongation after fracture (A), percentage reduction area (Z), and, if required, percentage total extension at the maximum force (A_{gt}), percentage plastic extension at maximum force (A_g)	7
10.4 Method of testing with expanded strain rate ranges (Method B)	7
10.4.1 General	7
10.4.2 Rate for the determination of yield strength or proof strength properties	7
10.4.3 Rate for the determination of tensile strength	7
10.5 Choice of the method and rates	8
10.6 Documentation of the chosen testing conditions	8
11 Determination or calculation of the properties	8
12 Test report	8
13 Measurement uncertainty	9
14 Figures	9

15	Annexes	10
	Annex A (informative) Additional information regarding test piece geometries used for testing at elevated temperature	11
	Annex B (informative) Measurement uncertainty	17
	Bibliography	20