

# ISO 13909-7:2001-12 (E)

## Hard coal and coke - Mechanical sampling - Part 7: Methods for determining the precision of sampling, sample preparation and test ing

---

<b>Contents</b>		<b>Page</b>
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Terms and definitions .....</b>	<b>1</b>
<b>4</b>	<b>General .....</b>	<b>2</b>
<b>5</b>	<b>Equations relating to factors affecting precision .....</b>	<b>3</b>
<b>6</b>	<b>Estimation of primary increment variance .....</b>	<b>4</b>
<b>7</b>	<b>Methods for estimating precision .....</b>	<b>6</b>
<b>8</b>	<b>Calculation of precision .....</b>	<b>10</b>
<b>9</b>	<b>Methods of checking sample preparation and testing errors .....</b>	<b>12</b>
<b>Annexes A Variogram method for determining variance .....</b>		<b>25</b>
<b>B</b>	<b>Grubbs' estimators method for determining sampling precision .....</b>	<b>32</b>
<b>Bibliography .....</b>		<b>40</b>