

# ISO 7539-6:2003-02 (E)

## Corrosion of metals and alloys - Stress corrosion testing - Part 6: P reparation and use of pre-cracked specimens for tests under constant load or constant displacement

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Terms and definitions .....</b>	<b>2</b>
<b>4</b>	<b>Principle .....</b>	<b>4</b>
<b>5</b>	<b>Specimens .....</b>	<b>5</b>
<b>6</b>	<b>Initiation and propagation of fatigue cracks .....</b>	<b>23</b>
<b>7</b>	<b>Procedure .....</b>	<b>25</b>
<b>8</b>	<b>Test report .....</b>	<b>33</b>
<b>Annex A (normative) Use of notched specimens for stress corrosion tests .....</b>		<b>35</b>
<b>Annex B (normative) Determination of crack growth velocity .....</b>		<b>38</b>