

# ISO 12800:2003-12 (E)

## Nuclear fuel technology - Guide to the measurement of the specific surface area of uranium oxide powders by the BET method

---

<b>Contents</b>		<b>Page</b>
<b>Foreword</b> .....		<b>iv</b>
<b>1</b>	<b>Scope</b> .....	<b>1</b>
<b>2</b>	<b>Principle</b> .....	<b>1</b>
2.1	Summary of the method .....	1
2.2	Isothermal adsorption curves .....	1
2.3	Conditions and assumptions .....	2
<b>3</b>	<b>Procedure</b> .....	<b>3</b>
3.1	Sample preparation .....	3
3.2	Volumetric measurement [3, 4] .....	3
3.3	Gravimetric measurement [5] .....	3
3.4	Original and single-point methods .....	3
3.5	Dynamic method (carrier gas method) .....	4
3.6	Alternative methods .....	4
<b>4</b>	<b>Expression of results</b> .....	<b>4</b>
4.1	Methods of calculation .....	4
4.2	Precision .....	6
<b>5</b>	<b>Test report</b> .....	<b>6</b>
<b>Bibliography</b> .....		<b>7</b>