

ISO 19318:2004-05 (E)

Surface chemical analysis - X-ray photoelectron spectroscopy - Reporting of methods used for charge control and charge correction

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative reference	1
3	Terms and definitions	1
4	Symbols and abbreviated terms	1
5	Apparatus	2
6	Calibration of binding-energy scale	2
7	Reporting of information related to charge control	2
7.1	Methods of charge control	2
7.2	Information on specimen	2
7.3	Instrument and operating conditions	3
7.4	General method for charge control	3
7.5	Reasons for needing charge control and for choosing the particular method for charge control	3
7.6	Values of experimental parameters	3
7.7	Information on the effectiveness of the method of charge control	4
8	Reporting of method(s) used for charge correction and the value of that correction	4
8.1	Methods of charge correction	4
8.2	Approach	4
8.3	Value of correction energy	4
Annex A (informative) Description of methods of charge control and charge correction		5
A.1	Introduction	5
A.2	Methods of charge control	5
A.3	Methods of charge correction	7
A.4	Bias referencing [17]	8
A.5	Auger parameter measurements [32-34]	9
Bibliography		10