

# ISO/TS 21432:2005-07 (E)

## Non-destructive testing - Standard test method for determining residual stresses by neutron diffraction

---

<b>Contents</b>		<b>Page</b>
Foreword .....		v
Introduction .....		vi
1	Scope .....	1
2	Normative references .....	1
3	Terms and definitions .....	2
4	Symbols and abbreviated terms .....	5
4.1	Symbols .....	5
4.2	Subscripts .....	6
4.3	Abbreviated terms .....	7
5	Summary of method .....	7
5.1	Preamble .....	7
5.2	Outline of principle -- Bragg's law .....	7
5.3	Neutron sources .....	7
5.4	Strain measurement .....	7
5.5	Neutron diffractometers .....	8
5.6	Stress determination .....	9
6	Preparations for measurements .....	12
6.1	Preamble .....	12
6.2	Alignment and calibration of the instrument .....	12
6.3	Choice of diffraction conditions .....	12
6.3.1	Monochromatic instruments .....	12
6.3.2	TOF instruments .....	15
6.4	Positioning procedures .....	15
6.5	Gauge volumes .....	15
6.6	Determination of a strain free or reference lattice spacing .....	16
7	Material characterization .....	18
7.1	Preamble .....	18
7.2	Composition .....	18
7.3	Thermal/mechanical history .....	18
7.4	Phases and crystal structures .....	18
7.5	Homogeneity .....	18
7.6	Microstructure .....	18
7.7	Texture .....	18
8	Recording requirements and measurement procedure .....	19
8.1	Preamble .....	19
8.2	Recording requirements .....	19
8.2.1	General information -- instrument .....	19
8.2.2	General information -- specimen .....	20
8.2.3	Specific information required for each strain measurement .....	20
8.3	Specimen co-ordinates .....	21
8.4	Positioning of the specimen .....	21
8.5	Measurement directions .....	21

8.6	Number and location of measuring positions .....	21
8.7	Gauge volume .....	21
8.8	Gauge volume centroid considerations .....	21
8.9	Temperature .....	22
9	Calculation of stress .....	22
9.1	Preamble .....	22
9.2	Normal stress determinations .....	22
9.3	Stress state determinations .....	23
9.3.1	The sin <sup>2</sup> method .....	23
9.4	Choice of elasticity constants .....	23
9.5	Data analysis .....	24
9.5.1	Peak fitting function .....	24
9.5.2	Background function .....	24
9.5.3	Peak to background ratio .....	24
9.5.4	Distorted peak profiles .....	24
10	Reliability of results .....	25
11	Reporting .....	25
11.1	Preamble .....	25
11.2	Strain or stress values .....	25
11.2.1	Stress free or reference lattice spacing .....	26
11.2.2	Conversion of strain to stress .....	26
11.2.3	Elasticity constants .....	26
11.2.4	Positioning .....	26
11.3	Neutron source and instrument .....	26
11.4	General measurement procedures .....	26
11.5	Specimens/materials properties .....	26
11.6	Original data .....	27
	Annex A (informative) Measurement procedures .....	28
	Annex B (informative) Determination of uncertainties in a measurand .....	36
	Bibliography .....	39