

ISO 1099:2006-04 (E)

Metallic materials - Fatigue testing - Axial force-controlled method

| Contents | | Page |
|--------------------|--|-------------|
| Foreword | | iv |
| Introduction | | v |
| 1 | Scope | 1 |
| 2 | Normative references | 1 |
| 3 | Terms and definitions | 1 |
| 4 | Test plan | 3 |
| 4.1 | General outline | 3 |
| 4.2 | Presentation of fatigue results | 4 |
| 4.2.1 | Wöhler or S-N curve | 4 |
| 4.2.2 | Mean stress diagrams | 4 |
| 4.2.3 | Alignment | 4 |
| 5 | Shape and size of specimen | 5 |
| 5.1 | Form of specimens | 5 |
| 5.2 | Specimen temperature measurement | 5 |
| 6 | Specimens | 6 |
| 6.1 | Geometry | 6 |
| 6.1.1 | Products (bars, flat sheets over 5 mm thick) | 6 |
| 6.1.2 | Flat products with thickness of 5 mm or less | 6 |
| 6.2 | Preparation of specimens | 7 |
| 6.2.1 | Machining procedure | 7 |
| 6.2.2 | Sampling and marking | 7 |
| 6.2.3 | Surface condition of the specimen | 8 |
| 6.2.4 | Dimensional checks | 8 |
| 6.2.5 | Storage and handling | 8 |
| 7 | Apparatus | 8 |
| 7.1 | Testing machine | 8 |
| 7.1.1 | Force transducer | 9 |
| 7.1.2 | Gripping of specimen | 9 |
| 7.1.3 | Alignment check | 9 |
| 7.2 | Instrumentation for test monitoring | 9 |
| 7.2.1 | Recording systems | 9 |
| 7.2.2 | Cycle counter | 9 |
| 7.3 | Checking and verification | 10 |
| 8 | Testing machine | 10 |
| 9 | Mounting of specimen | 10 |
| 10 | Speed of testing | 10 |
| 11 | Application of force | 11 |
| 12 | Recording of temperature and humidity | 11 |

| | | |
|-------------|--|-----------|
| 13 | Criterion of failure and test termination | 11 |
| 13.1 | Criterion of failure | 11 |
| 13.2 | Test termination | 11 |
| 14 | Test report | 12 |
| | Bibliography | 21 |