

# ISO 3262-4:2023-06 (E)

## Extenders - Specifications and methods of test - Part 4: Whiting

---

<b>Contents</b>		<b>Page</b>
	<b>Foreword</b> .....	<b>iv</b>
<b>1</b>	<b>Scope</b> .....	<b>1</b>
<b>2</b>	<b>Normative references</b> .....	<b>1</b>
<b>3</b>	<b>Terms and definitions</b> .....	<b>1</b>
<b>4</b>	<b>Requirements and test methods</b> .....	<b>2</b>
<b>5</b>	<b>Sampling</b> .....	<b>2</b>
<b>6</b>	<b>Determination of matter insoluble in hydrochloric acid</b> .....	<b>3</b>
	6.1 Reagents.....	3
	6.2 Apparatus.....	3
	6.3 Procedure.....	3
	6.4 Expression of results.....	3
<b>7</b>	<b>Test report</b> .....	<b>4</b>