

# ISO/TR 8550-3:2007-06 (E)

## Guidance on the selection and usage of acceptance sampling systems for inspection of discrete items in lots - Part 3: Sampling by variables

---

<b>Contents</b>		<b>Page</b>
<b>Foreword</b> .....		<b>iv</b>
<b>Introduction</b> .....		<b>v</b>
<b>1</b> <b>Scope</b> .....		<b>1</b>
<b>2</b> <b>Normative references</b> .....		<b>1</b>
<b>3</b> <b>Normality</b> .....		<b>2</b>
<b>4</b> <b>Types of control</b> .....		<b>12</b>
<b>5</b> <b>Forms of acceptance criteria</b> .....		<b>15</b>
<b>6</b> <b>International Standards for acceptance sampling of lots by variables</b> .....		<b>29</b>
<b>7</b> <b>Effect on the selection process of market and production conditions</b> .....		<b>31</b>
<b>Annex A (normative) Normal probability paper</b> .....		<b>38</b>
<b>Bibliography</b> .....		<b>39</b>