

# ISO 3951-4:2011-08 (E)

## Sampling procedures for inspection by variables - Part 4: Procedures for assessment of declared quality levels

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
1 <b>Scope</b> .....		1
2 <b>Normative references</b> .....		2
3 <b>Terms, definitions, symbols and abbreviations</b> .....		2
4 <b>Principles</b> .....		3
5 <b>Declared quality level (DQL)</b> .....		4
6 <b>Sampling plans</b> .....		5
7 <b>Operating a sampling plan</b> .....		8
8 <b>Further information</b> .....		15
<b>Annex A (informative) Method of matching variables plans to attributes plans</b> .....		20
<b>Annex B (informative) Examples of use of the procedures</b> .....		21
<b>Bibliography</b> .....		25