

ISO 3951-1:2013-09 (E)

Sampling procedures for inspection by variables - Part 1: Specification for single sampling plans indexed by acceptance quality limit (AQL) for lot-by-lot inspection for a single quality characteristic and a single AQL

Contents		Page
Foreword		vi
Introduction		viii
1	Scope	1
2	Normative references	1
3	Terms and definitions	2
4	Symbols	5
5	Acceptance quality limit (AQL)	6
5.1	Concept	6
5.2	Use	6
5.3	Specifying AQLs	6
5.4	Preferred AQLs	7
5.5	Caution	7
5.6	Limitation	7
6	Switching rules for normal, tightened, and reduced inspection	7
7	Relation to ISO 2859-1	7
7.1	Similarities	7
7.2	Differences	8
8	Consumer protection	9
8.1	Use of individual plans	9
8.2	Consumer's risk quality (CRQ) tables	9
8.3	Producer's risk tables	9
8.4	Operating characteristic (OC) curves	9
9	Allowing for measurement uncertainty	9
10	Planning	10
11	Choice between variables and attributes	10
12	Choice between the s-method and -method	11
13	Choice of inspection level and AQL	11
14	Choice of sampling scheme	11
14.1	Standard plans	11
14.2	Special plans	12
15	Preliminary operations	12
16	Standard procedures for the s-method	12

16.1	Obtaining a plan, sampling, and preliminary calculations	12
16.2	Acceptability criteria for single specification limits	13
16.3	Graphical method for a single specification limit	14
16.4	Acceptability criterion for combined control of double specification limits	15
16.4.1	General	15
16.4.2	Procedure for sample size 3	15
16.4.3	Procedure for sample size 4	17
16.4.4	Procedure for sample sizes greater than 4	18
17	Standard procedures for the -method	20
17.1	Obtaining a plan, sampling, and preliminary calculations	20
17.2	Acceptability criteria for a single specification limit	20
17.3	Acceptability criterion for combined control of double specification limits	21
18	Procedure during continuing inspection	22
19	Normality and outliers	23
19.1	Normality	23
19.2	Outliers	23
20	Records	23
20.1	Control charts	23
20.2	Lots that are not accepted	23
21	Operation of switching rules	23
22	Discontinuation and resumption of inspection	24
23	Switching between the s-method and -method	24
23.1	Estimating the process standard deviation	24
23.2	State of statistical control	25
23.3	Switching from the s-method to the -method	25
23.4	Switching from the -method to the s-method	25
24	Charts B to R -- Operating characteristic curves and tabulated values for single sampling plans, normal inspection: s-method	27
24.1	Operating characteristic curves and tabulated values for sample size code letter B: s-method	27
24.2	Operating characteristic curves and tabulated values for sample size code letter C: s-method	28
24.3	Operating characteristic curves and tabulated values for sample size code letter D: s-method	29
24.4	Operating characteristic curves and tabulated values for sample size code letter E: s-method	30
24.5	Operating characteristic curves and tabulated values for sample size code letter F: s-method	31
24.6	Operating characteristic curves and tabulated values for sample size code letter G: s-method	32
24.7	Operating characteristic curves and tabulated values for sample size code letter H: s-method	33
24.8	Operating characteristic curves and tabulated values for sample size code letter J: s-method	34
24.9	Operating characteristic curves and tabulated values for sample size code letter K: s-method	35
24.10	Operating characteristic curves and tabulated values for sample size code letter L: s-method	36
24.11	Operating characteristic curves and tabulated values for sample size code letter M: s-method	37
24.12	Operating characteristic curves and tabulated values for sample size code letter N: s-method	38

24.13	Operating characteristic curves and tabulated values for sample size code letter P: s-method	39
24.14	Operating characteristic curves and tabulated values for sample size code letter Q: s-method	40
24.15	Operating characteristic curves and tabulated values for sample size code letter R: s-method	41
25	Charts s-D to s-R -- Acceptance curves for combined control of double specification limits: s-method	42
Annex A (normative) Table for determining the sample size code letter		55
Annex B (normative) Form k for single sampling plans: s-method		56
Annex C (normative) Form k for single sampling plans: -method		59
Annex D (normative) Values of fs for maximum sample standard deviation (MSSD)		62
Annex E (normative) Values of f for maximum process standard deviation (MPSD)		65
Annex F (normative) Estimating the process fraction nonconforming for sample size 3: s-method ..		66
Annex G (normative) Single sampling plans of Form p*		69
Annex H (normative) Values of cU for upper control limit on the sample standard deviation		70
Annex I (normative) Supplementary acceptability constants for qualifying towards reduced inspection		71
Annex J (normative) Procedures for obtaining s and		72
Annex K (informative) Consumer's risk qualities		74
Annex L (informative) Producer's risks		78
Annex M (informative) Operating characteristics for the -method		82
Annex N (informative) Estimating the process fraction nonconforming for sample sizes 3 and 4: s-method		83
Annex O (normative) Accommodating measurement variability		86
Bibliography		91