

# ISO 3951-1:2013-09 (E)

## Sampling procedures for inspection by variables - Part 1: Specification for single sampling plans indexed by acceptance quality limit (AQL) for lot-by-lot inspection for a single quality characteristic and a single AQL

---

Contents	Page
Foreword .....	vi
Introduction .....	viii
1 Scope .....	1
2 Normative references .....	1
3 Terms and definitions .....	2
4 Symbols .....	5
5 Acceptance quality limit (AQL) .....	6
5.1 Concept .....	6
5.2 Use .....	6
5.3 Specifying AQLs .....	6
5.4 Preferred AQLs .....	7
5.5 Caution .....	7
5.6 Limitation .....	7
6 Switching rules for normal, tightened, and reduced inspection .....	7
7 Relation to ISO 2859-1 .....	7
7.1 Similarities .....	7
7.2 Differences .....	8
8 Consumer protection .....	9
8.1 Use of individual plans .....	9
8.2 Consumer's risk quality (CRQ) tables .....	9
8.3 Producer's risk tables .....	9
8.4 Operating characteristic (OC) curves .....	9
9 Allowing for measurement uncertainty .....	9
10 Planning .....	10
11 Choice between variables and attributes .....	10
12 Choice between the s-method and -method .....	11
13 Choice of inspection level and AQL .....	11
14 Choice of sampling scheme .....	11
14.1 Standard plans .....	11
14.2 Special plans .....	12
15 Preliminary operations .....	12
16 Standard procedures for the s-method .....	12

16.1	Obtaining a plan, sampling, and preliminary calculations .....	12
16.2	Acceptability criteria for single specification limits .....	13
16.3	Graphical method for a single specification limit .....	14
16.4	Acceptability criterion for combined control of double specification limits .....	15
16.4.1	General .....	15
16.4.2	Procedure for sample size 3 .....	15
16.4.3	Procedure for sample size 4 .....	17
16.4.4	Procedure for sample sizes greater than 4 .....	18
17	Standard procedures for the -method .....	20
17.1	Obtaining a plan, sampling, and preliminary calculations .....	20
17.2	Acceptability criteria for a single specification limit .....	20
17.3	Acceptability criterion for combined control of double specification limits .....	21
18	Procedure during continuing inspection .....	22
19	Normality and outliers .....	23
19.1	Normality .....	23
19.2	Outliers .....	23
20	Records .....	23
20.1	Control charts .....	23
20.2	Lots that are not accepted .....	23
21	Operation of switching rules .....	23
22	Discontinuation and resumption of inspection .....	24
23	Switching between the s-method and -method .....	24
23.1	Estimating the process standard deviation .....	24
23.2	State of statistical control .....	25
23.3	Switching from the s-method to the -method .....	25
23.4	Switching from the -method to the s-method .....	25
24	Charts B to R -- Operating characteristic curves and tabulated values for single sampling plans, normal inspection: s-method .....	27
24.1	Operating characteristic curves and tabulated values for sample size code letter B: s-method .....	27
24.2	Operating characteristic curves and tabulated values for sample size code letter C: s-method .....	28
24.3	Operating characteristic curves and tabulated values for sample size code letter D: s-method .....	29
24.4	Operating characteristic curves and tabulated values for sample size code letter E: s-method .....	30
24.5	Operating characteristic curves and tabulated values for sample size code letter F: s-method .....	31
24.6	Operating characteristic curves and tabulated values for sample size code letter G: s-method .....	32
24.7	Operating characteristic curves and tabulated values for sample size code letter H: s-method .....	33
24.8	Operating characteristic curves and tabulated values for sample size code letter J: s-method .....	34
24.9	Operating characteristic curves and tabulated values for sample size code letter K: s-method .....	35
24.10	Operating characteristic curves and tabulated values for sample size code letter L: s-method .....	36
24.11	Operating characteristic curves and tabulated values for sample size code letter M: s-method .....	37
24.12	Operating characteristic curves and tabulated values for sample size code letter N: s-method .....	38

24.13	Operating characteristic curves and tabulated values for sample size code letter P: s-method .....	39
24.14	Operating characteristic curves and tabulated values for sample size code letter Q: s-method .....	40
24.15	Operating characteristic curves and tabulated values for sample size code letter R: s-method .....	41
25	Charts s-D to s-R -- Acceptance curves for combined control of double specification limits: s-method .....	42
	<b>Annex A (normative) Table for determining the sample size code letter .....</b>	<b>55</b>
	<b>Annex B (normative) Form k for single sampling plans: s-method .....</b>	<b>56</b>
	<b>Annex C (normative) Form k for single sampling plans: -method .....</b>	<b>59</b>
	<b>Annex D (normative) Values of fs for maximum sample standard deviation (MSSD) .....</b>	<b>62</b>
	<b>Annex E (normative) Values of f for maximum process standard deviation (MPSD) .....</b>	<b>65</b>
	<b>Annex F (normative) Estimating the process fraction nonconforming for sample size 3: s-method ..</b>	<b>66</b>
	<b>Annex G (normative) Single sampling plans of Form p* .....</b>	<b>69</b>
	<b>Annex H (normative) Values of cU for upper control limit on the sample standard deviation .....</b>	<b>70</b>
	<b>Annex I (normative) Supplementary acceptability constants for qualifying towards reduced inspection .....</b>	<b>71</b>
	<b>Annex J (normative) Procedures for obtaining s and .....</b>	<b>72</b>
	<b>Annex K (informative) Consumer's risk qualities .....</b>	<b>74</b>
	<b>Annex L (informative) Producer's risks .....</b>	<b>78</b>
	<b>Annex M (informative) Operating characteristics for the -method .....</b>	<b>82</b>
	<b>Annex N (informative) Estimating the process fraction nonconforming for sample sizes 3 and 4: s-method .....</b>	<b>83</b>
	<b>Annex O (normative) Accommodating measurement variability .....</b>	<b>86</b>
	<b>Bibliography .....</b>	<b>91</b>