

# ISO 3951-2:2013-09 (E)

## Sampling procedures for inspection by variables - Part 2: General specification for single sampling plans indexed by acceptance quality limit (AQL) for lot-by-lot inspection of independent quality characteristics

---

<b>Contents</b>		<b>Page</b>
Foreword .....		vi
Introduction .....		viii
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>2</b>
<b>3</b>	<b>Terms and definitions .....</b>	<b>2</b>
<b>4</b>	<b>Symbols .....</b>	<b>6</b>
4.1	Univariate symbols .....	6
4.2	Multivariate symbols .....	8
<b>5</b>	<b>Acceptance quality limit (AQL) .....</b>	<b>8</b>
5.1	Concept .....	8
5.2	Use .....	8
5.3	Specifying AQLs .....	8
5.4	Preferred AQLs .....	9
5.5	Caution .....	9
5.6	Limitation .....	9
<b>6</b>	<b>Switching rules for normal, tightened, and reduced inspection .....</b>	<b>9</b>
7.1	Relation to ISO 2859-1 .....	10
7.1.1	Similarities to ISO 2859-1 .....	10
7.1.2	Differences from ISO 2859-1 .....	10
<b>8</b>	<b>Consumer protection .....</b>	<b>12</b>
8.1	Use of individual plans .....	12
8.2	Consumer's risk quality (CRQ) tables .....	12
8.3	Producer's risk tables .....	12
8.4	Operating characteristic (OC) curves .....	12
<b>9</b>	<b>Accommodating measurement variability .....</b>	<b>12</b>
<b>10</b>	<b>Planning .....</b>	<b>13</b>
<b>11</b>	<b>Choice between variables and attributes .....</b>	<b>13</b>
<b>12</b>	<b>Choice between the s-method and -method .....</b>	<b>14</b>
<b>13</b>	<b>Choice of inspection level and AQL .....</b>	<b>14</b>
<b>14</b>	<b>Choice of sampling scheme .....</b>	<b>14</b>
14.1	Standard plans .....	14
14.2	Special plans .....	15
<b>15</b>	<b>Preliminary operations .....</b>	<b>15</b>

16	Standard procedures for the univariate s-method .....	16
16.1	Obtaining a plan, sampling, and preliminary calculations .....	16
16.2	Form k acceptability criterion for the s-method .....	16
16.3	Form p* acceptability criterion for the s-method .....	18
16.3.1	Introduction .....	18
16.3.2	Combined control for the s-method .....	18
16.3.3	Separate control for the s-method .....	24
16.3.4	Complex control for the s-method .....	24
17	Standard multivariate s-method procedures for independent quality characteristics .....	24
17.1	General methodology .....	24
17.2	Example .....	25
18	Standard univariate -method procedures .....	27
18.1	Obtaining a plan, sampling, and preliminary calculations .....	27
18.2	Acceptability criterion for a single specification limit or for double specification limits with separate control .....	27
18.3	Acceptability criterion for double specification limits with combined or complex control .	28
19	Standard multivariate -method procedures for independent quality characteristics .....	30
19.1	General methodology .....	30
19.2	Example .....	31
20	Standard multivariate combined s-method and -method procedures for independent quality characteristics .....	32
20.1	General methodology .....	32
20.2	Example .....	33
21	Procedure during continuing inspection .....	35
22	Normality and outliers .....	35
22.1	Normality .....	35
22.2	Outliers .....	35
23	Records .....	35
23.1	Control charts .....	35
23.2	Lots that are not accepted .....	35
24	Operation of switching rules .....	36
25	Discontinuation and resumption of inspection .....	36
26	Switching between the s-method and -method .....	37
26.1	Estimating the process standard deviation .....	37
26.2	State of statistical control .....	37
26.3	Switching from the s-method to the -method .....	37
26.4	Switching from the -method to the s-method .....	37
	Annex A (normative) Table for determining the sample size code letter .....	38
	Annex B (normative) Form k single sampling plans: s-method .....	39
	Annex C (normative) Form k single sampling plans: -method .....	42
	Annex D (normative) Form p* single sampling plans: s-method .....	45
	Annex E (normative) Form p* single sampling plans: -method .....	48
	Annex F (normative) Values of fs for maximum sample standard deviation (MSSD) .....	51

<b>Annex G (normative) Values of <math>f</math> for maximum process standard deviation (MPSD) .....</b>	<b>54</b>
<b>Annex H (normative) Estimating the process fraction nonconforming for sample size 3: <math>s</math>-method ..</b>	<b>57</b>
<b>Annex I (normative) Values of <math>c_U</math> for upper control limit on the sample standard deviation .....</b>	<b>60</b>
<b>Annex J (normative) Supplementary acceptability constants for qualifying towards reduced inspection .....</b>	<b>61</b>
<b>Annex K (normative) Procedures for obtaining <math>s</math> and .....</b>	<b>62</b>
<b>Annex L (normative) Estimating the process fraction nonconforming .....</b>	<b>64</b>
<b>Annex M (informative) Consumer's risk qualities .....</b>	<b>70</b>
<b>Annex N (informative) Producer's risks .....</b>	<b>74</b>
<b>Annex O (informative) Operating characteristics for the <math>\bar{x}</math>-method .....</b>	<b>78</b>
<b>Annex P (informative) Accommodating measurement variability .....</b>	<b>79</b>
<b>Bibliography .....</b>	<b>85</b>