

ISO 3951-2:2013-09 (E)

Sampling procedures for inspection by variables - Part 2: General specification for single sampling plans indexed by acceptance quality limit (AQL) for lot-by-lot inspection of independent quality characteristics

Contents

	Page
Foreword	vi
Introduction	viii
1 Scope	1
2 Normative references	2
3 Terms and definitions	2
4 Symbols	6
4.1 Univariate symbols	6
4.2 Multivariate symbols	8
5 Acceptance quality limit (AQL)	8
5.1 Concept	8
5.2 Use	8
5.3 Specifying AQLs	8
5.4 Preferred AQLs	9
5.5 Caution	9
5.6 Limitation	9
6 Switching rules for normal, tightened, and reduced inspection	9
7.1 Relation to ISO 2859-1	10
7.1.1 Similarities to ISO 2859-1	10
7.1.2 Differences from ISO 2859-1	10
8 Consumer protection	12
8.1 Use of individual plans	12
8.2 Consumer's risk quality (CRQ) tables	12
8.3 Producer's risk tables	12
8.4 Operating characteristic (OC) curves	12
9 Accommodating measurement variability	12
10 Planning	13
11 Choice between variables and attributes	13
12 Choice between the s-method and -method	14
13 Choice of inspection level and AQL	14
14 Choice of sampling scheme	14
14.1 Standard plans	14
14.2 Special plans	15
15 Preliminary operations	15

16	Standard procedures for the univariate s-method	16
16.1	Obtaining a plan, sampling, and preliminary calculations	16
16.2	Form k acceptability criterion for the s-method	16
16.3	Form p* acceptability criterion for the s-method	18
16.3.1	Introduction	18
16.3.2	Combined control for the s-method	18
16.3.3	Separate control for the s-method	24
16.3.4	Complex control for the s-method	24
17	Standard multivariate s-method procedures for independent quality characteristics	24
17.1	General methodology	24
17.2	Example	25
18	Standard univariate -method procedures	27
18.1	Obtaining a plan, sampling, and preliminary calculations	27
18.2	Acceptability criterion for a single specification limit or for double specification limits with separate control	27
18.3	Acceptability criterion for double specification limits with combined or complex control .	28
19	Standard multivariate -method procedures for independent quality characteristics	30
19.1	General methodology	30
19.2	Example	31
20	Standard multivariate combined s-method and -method procedures for independent quality characteristics	32
20.1	General methodology	32
20.2	Example	33
21	Procedure during continuing inspection	35
22	Normality and outliers	35
22.1	Normality	35
22.2	Outliers	35
23	Records	35
23.1	Control charts	35
23.2	Lots that are not accepted	35
24	Operation of switching rules	36
25	Discontinuation and resumption of inspection	36
26	Switching between the s-method and -method	37
26.1	Estimating the process standard deviation	37
26.2	State of statistical control	37
26.3	Switching from the s-method to the -method	37
26.4	Switching from the -method to the s-method	37
Annex A (normative)	Table for determining the sample size code letter	38
Annex B (normative)	Form k single sampling plans: s-method	39
Annex C (normative)	Form k single sampling plans: -method	42
Annex D (normative)	Form p* single sampling plans: s-method	45
Annex E (normative)	Form p* single sampling plans: -method	48
Annex F (normative)	Values of fs for maximum sample standard deviation (MSSD)	51

Annex G (normative) Values of f for maximum process standard deviation (MPSD)	54
Annex H (normative) Estimating the process fraction nonconforming for sample size 3: s-method ..	57
Annex I (normative) Values of c_U for upper control limit on the sample standard deviation	60
Annex J (normative) Supplementary acceptability constants for qualifying towards reduced inspection	61
Annex K (normative) Procedures for obtaining s and	62
Annex L (normative) Estimating the process fraction nonconforming	64
Annex M (informative) Consumer's risk qualities	70
Annex N (informative) Producer's risks	74
Annex O (informative) Operating characteristics for the -method	78
Annex P (informative) Accommodating measurement variability	79
Bibliography	85