

# ISO 7870-7:2020-02 (E)

## Control charts - Part 7: Multivariate control charts

---

<b>Contents</b>		<b>Page</b>
Foreword		iv
Introduction		v
<b>1</b>	<b>Scope</b>	<b>1</b>
<b>2</b>	<b>Normative references</b>	<b>1</b>
<b>3</b>	<b>Terms and definitions</b>	<b>1</b>
<b>4</b>	<b>Abbreviated terms and symbols</b>	<b>2</b>
4.1	Abbreviated terms	2
4.2	Symbols	2
<b>5</b>	<b>Purpose and classification of multivariate control charts</b>	<b>4</b>
5.1	Purpose and applying conditions for multivariate control charts	4
5.2	Classification of multivariate control charts	5
<b>6</b>	<b>Multivariate control charts with unweighted averages for mean shift</b>	<b>6</b>
6.1	General	6
6.2	Control charts for the process mean ( $n > 1$ )	7
6.2.1	$\chi^2$ control chart when pre-specified parameter values are known	7
6.2.2	$T^2$ control chart when pre-specified parameter values are unknown	8
6.3	Control charts for the process mean ( $n = 1$ )	8
6.3.1	$\chi^2$ control chart when pre-specified parameter values are known	8
6.3.2	$T^2$ control chart when pre-specified parameter values are unknown	9
6.4	Summary and selection of multivariate control charts with unweighted averages for mean shifts	9
6.5	Test for assignable causes	10
<b>7</b>	<b>Multivariate control charts with weighted averages for mean shifts</b>	<b>11</b>
<b>8</b>	<b>Control charts for the process dispersion</b>	<b>12</b>
<b>9</b>	<b>Interpretation of an out-of-control signal</b>	<b>13</b>
<b>Annex A</b> (informative)	<b>Example of multivariate statistical process control</b>	<b>14</b>
<b>Annex B</b> (informative)	<b>Example of MEWMA control chart</b>	<b>17</b>
<b>Annex C</b> (informative)	<b>Estimation of <math>\mu</math> and <math>\Sigma</math></b>	<b>23</b>
<b>Bibliography</b>		<b>25</b>