

ISO 24481-1:2026-08 (E)

Statistical methods for implementation of Six Sigma - Exploratory data analysis - Part 1: General methodology

Contents	Page
Foreword	iv
Introduction	v
1 Scope	1
2 Normative references	1
3 Terms and definitions	1
4 Symbols and abbreviated terms	3
5 Fundamental concepts	3
5.1 General	3
5.2 Different types of data sets and possible challenges encountered within EDA	4
5.3 Relation and difference between data visualization (DV) and EDA	5
5.4 Principles and related steps for conducting EDA	5
6 Tools of EDA from different perspectives	6
6.1 General	6
6.2 Certain tools for the different types of data	6
6.2.1 Discrete data	6
6.2.2 Continuous data	7
6.3 Sorted according to their objectives	8
6.4 EDA tools used in each phase of DMAIC	8
7 Emphases and cautions for certain tools and other aspects of EDA	9
7.1 General	9
7.2 Importance of checking the metadata	9
7.3 Cautions about some graphical methods	10
7.3.1 Use graphical methods efficiently	10
7.3.2 Bar charts or dot charts instead of pie charts	11
7.3.3 Avoid misleading graphs and note the data Inking issue	11
7.3.4 Causation is more important than correlation	11
7.3.5 The relationship between EDA and CDA or other tools	12
7.3.6 Choosing suitable data analysis software packages is important for EDA	12
Annex A (informative) Comparison of data visualization and EDA from different aspects	13
Annex B (informative) Some concrete EDA principles in Six Sigma and quality improvement projects	14
Annex C (informative) Limitation of descriptive statistics and a typical example	16
Bibliography	17