

ISO 2859-4:2002-08 (E)

Sampling procedures for inspection by attributes - Part 4: Procedures for assessment of declared quality levels

Contents		Page
1	Scope	1
2	Normative references	2
3	Terms, definitions, symbols and abbreviations	2
4	Principles	3
5	Declared quality level (DQL)	4
6	Sampling plans	4
7	Operating a sampling plan	6
8	Further information	7
Annex A Examples of use of the procedures		11
A.1	Example 1	11
A.2	Example 2	11
A.3	Example 3	11