

ISO 3951-1:2005-04 (E)

Sampling procedures for inspection by variables - Part 1: Specification for single sampling plans indexed by acceptance quality limit (AQL) for lot-by-lot inspection for a single quality characteristic and a single AQL

Contents		Page
Foreword		v
Introduction		vii
1	Scope	1
2	Normative references	2
3	Terms and definitions	2
4	Symbols	5
5	Acceptance quality limit (AQL)	7
5.1	Principle	7
5.2	Use	7
5.3	Specifying AQLs	7
5.4	Preferred AQLs	7
5.5	Caution	7
5.6	Limitation	7
6	Switching rules for normal, tightened and reduced inspection	7
7	Relation to ISO 2859-1	8
7.1	Similarities	8
7.2	Differences	8
8	Limiting quality protection	9
8.1	Use of individual plans	9
8.2	Consumer's risk quality tables	9
8.3	Producer's risk tables	9
8.4	Operating characteristic curves	9
9	Planning	10
10	Choice between variables and attributes	10
11	Choice between the "s" and "" methods	11
12	Choice of inspection level and AQL	11
13	Choice of sampling plan	11
13.1	Standard plans	11
13.2	Special plans	12
14	Preliminary operations	12
15	Standard procedure for the "s" method	12
15.1	Obtaining a plan, sampling and preliminary calculations	12
15.2	Acceptability criteria for single specification limits	13

15.3	Graphical method for a single specification limit	14
15.4	Acceptability criterion for combined control of double specification limits	15
16	Standard procedure for the "" method	21
16.1	Obtaining a plan, sampling and preliminary calculations	21
16.2	Acceptability criteria for a single specification limit	21
16.3	Acceptability criterion for combined control of double specification limits	22
17	Procedure during continuing inspection	23
18	Normality and outliers	24
18.1	Normality	24
18.2	Outliers	24
19	Records	24
19.1	Control charts	24
19.2	Lots that are not accepted	24
20	Operation of switching rules	24
21	Discontinuation and resumption of inspection	25
22	Switching between the "s" and "" methods	25
22.1	Estimating the process standard deviation	25
22.2	State of statistical control	26
22.3	Switching from the "s" method to the "" method	26
22.4	Switching from the "" method to the "s" method	26
23	Chart A -- Sample-size code letters of standard single sampling plans for specified quality levels	26
24	Charts B to R (Figures 5 to 19) -- Operating characteristic curves and tabulated values for sample-size code letter B to R: "s" method	28
25	Charts s-D to s-R (Figures 20 to 32) -- Acceptance curves for combined control of double specification limits: "s" method	56
Annex A (normative)	Tables for determining the appropriate sample size	69
Annex B (normative)	Form k single sampling plans for the "s" method	71
Annex C (normative)	Form k single sampling plans for the "" method	75
Annex D (normative)	Values of f_s for maximum sample standard deviation (MSSD)	79
Annex E (normative)	Values of f for maximum process standard deviation (MPSD)	83
Annex F (normative)	Estimating the process fraction nonconforming for sample size 3: "s" method	84
Annex G (normative)	Type p^* single sampling plans	87
Annex H (normative)	Values of c_u for upper control limit on the sample standard deviation	88
Annex I (normative)	Supplementary acceptability constants for qualifying towards reduced inspection	89
Annex J (normative)	Procedures for obtaining s and	90
Annex K (informative)	Consumer's risk qualities	92
Annex L (informative)	Producer's risks	96

Annex M (informative) Operating characteristics for the "" method 100

**Annex N (informative) Estimating the process fraction nonconforming for sample sizes 3 and 4 --
"s" method 101**

Bibliography 103