

# ISO 3951-2:2006-04 (E)

## Sampling procedures for inspection by variables - Part 2: General specification for single sampling plans indexed by acceptance quality limit (AQL) for lot-by-lot inspection of independent quality characteristics

---

### Contents

	Page
Foreword .....	v
Introduction .....	vii
1 Scope .....	1
2 Normative references .....	1
3 Terms and definitions .....	2
4 Symbols .....	6
5 Acceptance quality limit (AQL) .....	8
6 Switching rules for normal, tightened and reduced inspection .....	9
8 Consumer protection .....	12
9 Planning .....	13
10 Choice between variables and attributes .....	13
11 Choice between the "s" and "" methods .....	14
12 Choice of inspection level and AQL .....	14
13 Choice of sampling scheme .....	15
14 Preliminary operations .....	17
15 Standard univariate "s" method procedures .....	17
16 Standard multivariate "s" method procedures for independent quality characteristics .....	26
17 Standard univariate "" method procedures .....	28
18 Standard multivariate "" method procedures for independent quality characteristics .....	31
19 Standard multivariate combined "s" and "" method procedures for independent quality characteristics .....	32
20 Procedure during continuing inspection .....	34
21 Normality and outliers .....	34
22 Records .....	34
23 Operation of switching rules .....	35

<b>24</b>	<b>Discontinuation and resumption of inspection .....</b>	<b>36</b>
<b>25</b>	<b>Switching between the "s" and "" methods .....</b>	<b>36</b>
<b>Annex A (normative) Tables for determining the appropriate sample size .....</b>		<b>37</b>
<b>Annex B (normative) Form k single sampling plans for the "s" method .....</b>		<b>39</b>
<b>Annex C (normative) Form k single sampling plans for the "" method .....</b>		<b>43</b>
<b>Annex D (normative) Values of fs for maximum sample standard deviation (MSSD) .....</b>		<b>47</b>
<b>Annex E (normative) Values of f process standard deviation .....</b>		<b>51</b>
<b>Annex F (normative) Estimating the process fraction nonconforming for sample size 3: "s" method .....</b>		<b>54</b>
<b>Annex G (normative) Form p* single sample plans .....</b>		<b>57</b>
<b>Annex H (normative) Values of cU for upper control limit on the sample standard deviation .....</b>		<b>61</b>
<b>Annex I (normative) Supplementary acceptability constants for qualifying towards reduced inspection .....</b>		<b>62</b>
<b>Annex J (normative) Procedures for obtaining s or .....</b>		<b>63</b>
<b>Annex K (normative) Estimating the process fraction nonconforming .....</b>		<b>65</b>
<b>Annex L (informative) Consumer's risk qualities .....</b>		<b>69</b>
<b>Annex M (informative) Producer's risks .....</b>		<b>74</b>
<b>Annex N (informative) Operating characteristics for the "" method .....</b>		<b>79</b>
<b>Bibliography .....</b>		<b>80</b>