

ISO/TR 18931:2001-06 (E)

Imaging materials - Recommendations for humidity measurement and control

Contents		Page
Foreword		iv
Introduction		v
1 Scope		1
2 Terms and definitions		1
3 Moisture content of gases		2
4 Measuring systems		2
5 Sensor location		5
6 Recommendations		5
Annex A Importance of relative humidity		6
Annex B Humidity control in storage areas		7
Bibliography		8