

ISO 230-1:1996-07 (E)

Test code for machine tools - Part 1: Geometric accuracy of machines operating under no-load or finishing conditions

Contents		Page
1	Scope	1
2	General considerations	1
2.1	Definitions relating to geometric tests	1
2.2	Test methods and use of measuring instruments	1
2.3	Tolerances.....	2
2.31	Tolerances on measurements when testing machine tools	2
2.311	Units of measurement and measuring ranges	2
2.312	Rules concerning tolerances	2
2.32	Subdivisions of tolerances.....	2
2.321	Tolerances applicable to test pieces and to individual components of machine tools.....	2
2.321.1	Tolerances of dimension	2
2.321.2	Tolerances of form	3
2.321.3	Tolerances of Position	3
2.321.4	Influence of errors of form in determining positional errors.....	3
2.321.5	Local tolerances	3
2.322	Tolerances applicable to the displacement of a component of a machine tool	4
2.322.1	Tolerances of positioning.....	4
2.322.11	Tolerances of repeatability.....	4
2.322.2	Tolerances of the form of trajectory.....	4
2.322.3	Tolerances of relative position of straight-line motion	4
2.322.4	Local tolerance of displacement of a component.....	5
2.323	Overall or inclusive tolerances	5
2.324	Symbols and positions of tolerances for relative angular positions of axes, slideways, etc	5
2.325	Conventional definition of the axes and of the movements	5
3	Preliminary Operations	5
3.1	Installation of the machine before test	5
3.11	Levelling	5
3.2	Conditions of the machine before test.....	5
3.21	Dismantling of certain components	5
3.22	Temperature conditions of certain components before test	5
3.23	Functioning and loading.....	6
4	Machining tests	6
4.1	Testing	6
4.2	Checking of workpieces in machining tests	6
5	Geometric tests	6
5.1	General	6
5.2	Straightness.....	6
5.21	Straightness of a line in a plane or in space	7
5.211	Definition	7
5.211.1	Straightness of a line in a plane	7
5.211.2	Straightness of a line in space.....	7
5.212	Methods of measurement of straightness.....	7
5.212.1	Methods based on the measurement of length.....	7
5.212.11	Straightedge method(formerly 5.212.1)	8
5.212.111	Measurement in a vertical plane	8
5.212.112	Measurement in a horizontal plane	8
5.212.12	Taut-wire and microscope method(formerly 5.212.3).....	9

5.212.13	Alignment telescope method.....	10
5.212.14	Alignment laser technique.....	10
5.212.15	Laser interferometry technique.....	10
5.212.2	Methods based on the measurement of angles	11
5.212.21	Precision level method.....	11
5.212.22	Autocollimation method.....	12
5.212.23	Method by laser interferometer (angle measurement)	12
5.213	Tolerance.....	13
5.213.1	Definition	13
5.213.2	Determination of tolerance	13
5.22	Straightness of components	13
5.221	Definition	13
5.222	Methods of straightness measurement.....	13
5.222.1	Reference grooves or reference surface of tables.....	13
5.222.2	Slideways.....	14
5.222.21	Vee surfaces.....	14
5.222.22	Cylindrical surfaces.....	14
5.222.23	Single vertical surfaces.....	15
5.222.24	Slant-bed configuration	15
5.222.3	Tolerances.....	15
5.23	Straight-line motion.....	15
5.231	Definitions	15
5.231.1	Positional deviations.....	15
5.231.2	Linear deviations	15
5.231.3	Angular deviations	16
5.232	Methods of measurement.....	16
5.232.1	Methods of measurement of linear deviations	16
5.232.11	Method with a straightedge and a dial gauge (formerly 5.232.1).....	16
5.232.12	Method with microscope and taut wire (formerly 5.232.2)	16
5.232.13	Method using an alignment telescope	16
5.232.14	Method using a laser	16
5.232.15	Method using angle measurements	16
5.232.2	Methods of measurement of angular deviation.....	16
5.232.21	Method using a precision level	17
5.232.22	Method using an autocollimator	17
5.232.23	Method using a laser	17
5.233	Tolerance	17
5.233.1	Tolerance for the linear deviation of straight-line motion.....	17
5.233.2	Tolerance for the angular deviation of straight-line motion	17
5.3	Flatness	17
5.31	Definition	17
5.32	Methods of measurement	17
5.321	Measurement of flatness by means of a surface plate	17
5.321.1	Measurement by means of a surface plate and a dial gauge.....	17
5.322	Measurement of flatness by means of straightedge(s)	18
5.322.1	Measurement by means of a family of straight lines by displacement of a straightedge(formerly 5.322)	18
5.322.2	Measurement by means of straightedges, a precision level and a dial gauge	18
5.323	Measurement of flatness by means of a precision level	19
5.323.1	Measurement of a rectangular surface.....	19
5.323.2	Measurement of plane surfaces with circular contours	19
5.324	Measurement of flatness by optical methods.....	20
5.324.1	Measurement by an autocollimator	20
5.324.2	Measurement by a sweep optical Square	20
5.324.3	Measurement by an alignment laser.....	21
5.324.4	Measurement by a laser measuring system	21
5.325	Measurement by a coordinate measuring machine.....	22
5.33	Tolerances	22
5.4	Parallelism, equidistance and coincidence	22
5.41	Parallelism of lines and planes	22
5.411	Definitions	22
5.412	Methods of measurement	22

5.412.1	General, for axes	22
5.412.2	Parallelism of two planes	23
5.412.21	Straightedge and dial gauge	23
5.412.22	Precision level method	23
5.412.3	Parallelism of two axes	23
5.412.31	Plane passing through two axes	23
5.412.32	Second plane perpendicular to the first	23
5.412.4	Parallelism of an axis to a plane	24
5.412.5	Parallelism of an axis to the intersection of two planes	24
5.412.6	Parallelism of the intersection of two planes to a third plane	24
5.412.7	Parallelism between two straight lines, each formed by the intersection of two planes	25
5.413	Tolerances.....	25
5.42	Parallelism of motion	25
5.421	Definition	25
5.422	Methods of measurement.....	26
5.422.1	General	26
5.422.2	Parallelism between a trajectory and a plane.....	26
5.422.21	Plane is on the moving component itself	26
5.422.22	Plane is not on the moving component itself.....	26
5.422.3	Parallelism of a trajectory to an axis.....	26
5.422.4	Parallelism of a trajectory to the intersection of two planes	27
5.422.5	Parallelism between two trajectories	27
5.423	Tolerance.....	27
5.43	Equidistance	27
5.431	Definition	27
5.432	Methods of measurement.....	27
5.432.1	General	27
5.432.2	Special case of the equidistance of two axes from the plane of pivoting of one of the axes.....	27
5.433	Tolerance.....	28
5.44	Coaxiality, coincidence or alignment.....	28
5.441	Definition	28
5.442	Method of measurement.....	28
5.443	Tolerance.....	29
5.5	Squareness or perpendicularity	29
5.51	Squareness of straight lines and planes	29
5.511	Definition	29
5.512	Methods of measurement.....	29
5.512.1	General	29
5.512.2	Two planes at 90° to each other.....	30
5.512.3	Two axes at 90° to each other	30
5.512.31	The two axes are fixed axes	30
5.512.32	One of the axes is an axis of rotation	30
5.512.4	An axis and a plane at 90° to each other	30
5.512.41	Fixed axis	30
5.512.42	Axis of rotation	30
5.512.5	An axis at 90° to the intersection of two planes.....	30
5.512.51	Fixed axis	30
5.512.52	Axis of rotation	31
5.512.6	When the intersection of two planes is at 90° to another plane.....	31
5.512.7	When two straight lines, each formed by the intersection of two planes, are at 90° to each other	31
5.513	Tolerance.....	31
5.52	Perpendicularity of motion	31
5.521	Definition	31
5.522	Methods of measurement.....	31
5.522.1	General	31
5.522.2	Perpendicularity between the trajectory of a point and a plane.....	32
5.522.3	Trajectory of a point at 90° to an axis	32
5.522.4	Two trajectories perpendicular to each other	32
5.523	Tolerance.....	32
5.6	Rotation	32

5.61	Run-out	33
5.611	Definitions	33
5.611.1	Out-of-round.....	33
5.611.2	Eccentricity	33
5.611.3	Radial throw of an axis at a given point	33
5.611.4	Run-out of a component at a given section.....	33
5.612	Methods of measurement	33
5.612.1	Precautions before testing	33
5.612.2	External surface	34
5.612.3	Internal surface	34
5.613	Tolerance.....	34
5.62	Periodic axial Slip	35
5.621	Definitions	35
5.621.1	Minimum axial play.....	35
5.621.2	Periodic axial Slip.....	35
5.622	Methods of measurement	35
5.622.1	General.....	35
5.622.2	Applications	35
5.623	Tolerance	35
5.63	Camming.....	36
5.631	Definitions	36
5.632	Method of measurement	36
5.633	Tolerance.....	36
6	Special tests.....	37
6.1	Division	37
6.11	Definition of errors	37
6.111	Individual error of division.....	37
6.112	Successive error of division.....	37
6.1	13 Local error of division	37
6.114	Cumulative error	37
6.115	Total error of division.....	37
6.116	Graphical representation of these errors.....	37
6.12	Methods of measurement	39
6.13	Tolerance	39
6.2	Determination of the linear positioning deviations of screw-driven components	39
6.3	Angular play	39
6.31	Definition	39
6.32	Method of measurement (testing of the indexing device/component)	39
6.33	Tolerance	39
6.4	Repeatability of devices with angular indexing.....	39
6.41	Definition	39
6.42	Method of measurement	40
6.43	Tolerance	40
6.5	Intersection of axes	40
6.51	Definition	40
6.52	Methods of measurement	40
6.521	Direct measurement	40
6.522	Indirect measurement	40
6.53	Tolerance	40
6.6	Circularity	40
6.61	Definition	40
6.62	methods of measurement on test pieces.....	40
6.621	Circularity measuring machine with rotating pickup or rotating table	40
6.622	Coordinate measuring machine	41
6.623	Projection of the profile	41
6.624	Vee-block method.....	41
6.63	Measurement of numerically controlled (NC) circular movements.....	41
6.631	Rotating one-dimensional probe	41
6.632	Circular master and two-dimensional probe	41
6.633	Telescopic ball bar	43
6.7	Cylindricity	43

6.71	Definition	43
6.72	Methods of measurement.....	43
6.721	Coordinate measuring machine.....	43
6.722	Circularity measuring machine with rotating pickup or rotating table.....	44
6.723	Vee-block method	44
6.8	Consistency of machined diameters.....	44
6.81	Definition	44
6.82	Methods of measurement.....	44
6.821	Micrometer or similar two-point measuring Instrument	44
6.822	Height gauge.....	44

Annexes

A	Instruments and equipment for testing machine tools.....	45
A.1	General.....	45
A.2	Straightedges	45
A.3	Test mandrels with taper shanks	46
A.4	Mandrels between centres	51
A.5	Squares.....	52
A.6	Precision levels.....	54
A.7	Linear displacement probes	55
A.8	Surface plates	56
A.9	Microscopes with taut-wire.....	56
A.10	Alignment telescopes.....	57
A.11	Autocollimators.....	58
A.12	Sweep optical squares	59
A.13	Laser interferometers	59
B	Bibliograph	62