

# ISO 1701-1:2004-08 (E)

## Test conditions for milling machines with table of variable height - Testing of the accuracy - Part 1: Machines with horizontal spindle

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Terminology, designation of axes and milling operations .....</b>	<b>1</b>
<b>3.1</b>	<b>Terminology and designation of axes .....</b>	<b>1</b>
<b>3.2</b>	<b>Milling operations .....</b>	<b>4</b>
<b>3.3</b>	<b>Description of machines .....</b>	<b>4</b>
<b>4</b>	<b>Preliminary remarks .....</b>	<b>5</b>
<b>4.1</b>	<b>Measuring units .....</b>	<b>5</b>
<b>4.2</b>	<b>Reference to ISO 230-1 .....</b>	<b>5</b>
<b>4.3</b>	<b>Testing sequence .....</b>	<b>5</b>
<b>4.4</b>	<b>Tests to be performed .....</b>	<b>5</b>
<b>4.5</b>	<b>Measuring instruments .....</b>	<b>5</b>
<b>4.6</b>	<b>Machining tests .....</b>	<b>6</b>
<b>4.7</b>	<b>Minimum tolerance .....</b>	<b>6</b>
<b>5</b>	<b>Geometric tests .....</b>	<b>7</b>
<b>5.1</b>	<b>Axes of motion .....</b>	<b>7</b>
<b>5.2</b>	<b>Table .....</b>	<b>10</b>
<b>5.3</b>	<b>Spindle .....</b>	<b>15</b>
<b>5.4</b>	<b>Arbor support .....</b>	<b>20</b>
<b>6</b>	<b>Machining test .....</b>	<b>24</b>
<b>Annex A (informative)</b>	<b>Equivalent terms in German, Italian, Dutch, Spanish and Swedish, corresponding to Figure 1 .....</b>	<b>25</b>
<b>Annex B (informative)</b>	<b>Equivalent terms in German, Italian, Dutch, Spanish and Swedish, corresponding to Figure 2 .....</b>	<b>26</b>
<b>Bibliography .....</b>		<b>27</b>