

# ISO 17295:2023-01 (E)

## Additive manufacturing - General principles - Part positioning, coordinates and orientation

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
1	<b>Scope .....</b>	<b>1</b>
2	<b>Normative references .....</b>	<b>1</b>
3	<b>Terms and definitions .....</b>	<b>1</b>
4	<b>Machine coordinate systems for additive manufacturing machines with different build directions .....</b>	<b>1</b>
4.1	<b>General .....</b>	<b>1</b>
4.2	<b>Machine coordinate system for additive manufacturing machines with upwards Z-positive build direction .....</b>	<b>1</b>
4.3	<b>Machine coordinate system for additive manufacturing machines with downwards Z-positive build direction .....</b>	<b>2</b>
5	<b>Rule for positive direction of axes of rotation .....</b>	<b>3</b>
6	<b>Bounding box .....</b>	<b>3</b>
7	<b>Initial build orientation .....</b>	<b>4</b>
8	<b>Orthogonal orientation notation .....</b>	<b>6</b>
8.1	<b>General .....</b>	<b>6</b>
8.2	<b>Bilateral symmetry .....</b>	<b>7</b>
8.3	<b>Abbreviation of orthogonal orientation notation .....</b>	<b>8</b>
9	<b>Representation of part location and initial build orientation .....</b>	<b>8</b>
10	<b>Representation of part location and reorientation .....</b>	<b>9</b>
Bibliography .....		12