

# ISO/ASTM 52933:2024-03 (E)

**Additive manufacturing - Environment, health and safety - Test method for the hazardous substances emitted from material extrusion type 3D printers in the non-industrial places**

---

<b>Contents</b>		<b>Page</b>
<b>Foreword</b>		<b>iv</b>
<b>Introduction</b>		<b>v</b>
<b>1</b>	<b>Scope</b>	<b>1</b>
<b>2</b>	<b>Normative references</b>	<b>1</b>
<b>3</b>	<b>Terms and definitions</b>	<b>2</b>
<b>4</b>	<b>Hazardous substance targets and major factors</b>	<b>3</b>
<b>5</b>	<b>Relevant test standards</b>	<b>3</b>
<b>6</b>	<b>Sampling conditions</b>	<b>4</b>
6.1	Sampling location	4
6.2	Sampling planning	4
<b>7</b>	<b>Measurement methods</b>	<b>6</b>
7.1	Active and time-integrated methods	6
7.1.1	Purpose	6
7.1.2	VOCs analysis	6
7.1.3	Aldehyde method	9
7.2	Real-time method	11
7.2.1	Purpose	11
7.2.2	Sampling	11
7.2.3	Determination of particles concentration	11
<b>8</b>	<b>Test report</b>	<b>13</b>
<b>Annex A (informative)</b>	<b>Considerations for reducing the emission of hazardous substances</b>	<b>15</b>
<b>Annex B (informative)</b>	<b>Checklist for reduction of hazardous substances</b>	<b>22</b>
<b>Bibliography</b>		<b>23</b>