

# ISO 7503-1:2016-01 (E)

## Measurement of radioactivity - Measurement and evaluation of surface contamination - Part 1: General principles

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Terms and definitions, symbols and abbreviations .....</b>	<b>2</b>
<b>3.1</b>	<b>Terms and definitions .....</b>	<b>2</b>
<b>3.2</b>	<b>Symbols and abbreviated terms .....</b>	<b>3</b>
<b>4</b>	<b>Objectives of surface contamination measurements .....</b>	<b>4</b>
<b>4.1</b>	<b>General .....</b>	<b>4</b>
<b>4.2</b>	<b>National and international regulations .....</b>	<b>4</b>
<b>4.3</b>	<b>Definition of the measuring programme .....</b>	<b>4</b>
<b>5</b>	<b>Direct and indirect methods of assessing surface contamination .....</b>	<b>5</b>
<b>5.1</b>	<b>General .....</b>	<b>5</b>
<b>5.2</b>	<b>Direct method .....</b>	<b>6</b>
<b>5.3</b>	<b>Indirect method (wipe tests) .....</b>	<b>6</b>
<b>5.4</b>	<b>Wipe test uncertainties .....</b>	<b>6</b>
<b>6</b>	<b>Radionuclide identification and spectral analysis .....</b>	<b>6</b>
<b>7</b>	<b>Monitoring instruments .....</b>	<b>7</b>
<b>7.1</b>	<b>Selection of monitors .....</b>	<b>7</b>
<b>7.2</b>	<b>Introduction to the calibration of surface contamination instruments for direct measurement .....</b>	<b>7</b>
<b>7.3</b>	<b>Tests before first use (TBFU) .....</b>	<b>8</b>
<b>7.4</b>	<b>Periodic calibration .....</b>	<b>9</b>
<b>7.5</b>	<b>Function check .....</b>	<b>9</b>
<b>8</b>	<b>Estimation of surface contamination monitor response and calibration factors .....</b>	<b>9</b>
<b>8.1</b>	<b>General .....</b>	<b>9</b>
<b>8.2</b>	<b>Relationship between surface emission rate and activity .....</b>	<b>10</b>
<b>9</b>	<b>Evaluation of measurement data .....</b>	<b>12</b>
<b>10</b>	<b>Uncertainties .....</b>	<b>12</b>
<b>10.1</b>	<b>General .....</b>	<b>12</b>
<b>10.2</b>	<b>Assessment of uncertainty in the calibration factor .....</b>	<b>12</b>
<b>10.3</b>	<b>Assessment of uncertainty in the measurement .....</b>	<b>13</b>
<b>10.4</b>	<b>Wipe test uncertainties .....</b>	<b>14</b>
<b>11</b>	<b>Test report for a surface contamination instrument .....</b>	<b>14</b>
<b>Annex A (informative) Calibration of surface contamination instruments .....</b>		<b>16</b>
<b>Annex B (informative) Example of surface contamination estimation .....</b>		<b>21</b>

<b>Annex C (informative) Calibration of dose rate measuring instruments .....</b>	<b>23</b>
<b>Bibliography .....</b>	<b>25</b>