

# ISO 7503-1:2016-01 (E)

## Measurement of radioactivity - Measurement and evaluation of surface contamination - Part 1: General principles

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
1	Scope .....	1
2	Normative references .....	1
3	Terms and definitions, symbols and abbreviations .....	2
3.1	Terms and definitions .....	2
3.2	Symbols and abbreviated terms .....	3
4	Objectives of surface contamination measurements .....	4
4.1	General .....	4
4.2	National and international regulations .....	4
4.3	Definition of the measuring programme .....	4
5	Direct and indirect methods of assessing surface contamination .....	5
5.1	General .....	5
5.2	Direct method .....	6
5.3	Indirect method (wipe tests) .....	6
5.4	Wipe test uncertainties .....	6
6	Radionuclide identification and spectral analysis .....	6
7	Monitoring instruments .....	7
7.1	Selection of monitors .....	7
7.2	Introduction to the calibration of surface contamination instruments for direct measurement .....	7
7.3	Tests before first use (TBFU) .....	8
7.4	Periodic calibration .....	9
7.5	Function check .....	9
8	Estimation of surface contamination monitor response and calibration factors .....	9
8.1	General .....	9
8.2	Relationship between surface emission rate and activity .....	10
9	Evaluation of measurement data .....	12
10	Uncertainties .....	12
10.1	General .....	12
10.2	Assessment of uncertainty in the calibration factor .....	12
10.3	Assessment of uncertainty in the measurement .....	13
10.4	Wipe test uncertainties .....	14
11	Test report for a surface contamination instrument .....	14
Annex A (informative)	Calibration of surface contamination instruments .....	16
Annex B (informative)	Example of surface contamination estimation .....	21

<b>Annex C (informative) Calibration of dose rate measuring instruments .....</b>	<b>23</b>
<b>Bibliography .....</b>	<b>25</b>