

ISO 7503-3:2016-01 (E)

Measurement of radioactivity - Measurement and evaluation of surface contamination - Part 3: Apparatus calibration

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms, definitions, symbols, and abbreviated terms	2
3.1	Terms and definitions	2
3.2	Symbols and abbreviated terms	2
4	Surface contamination evaluation methods	3
5	Principal direct calibration methodology including summation correction	4
5.1	General	4
5.2	Calibration for radionuclides with single emission decay schemes	4
5.3	P-factor for radionuclides with uncomplex decay schemes	6
5.4	P-factors for radionuclides with complex decay schemes	7
5.5	Generic estimation of instrument response	8
5.5.1	Determination of the energy response of the instrument	8
5.5.2	Modelling of the decay paths of the radionuclide of interest	9
5.5.3	Determination of the overall instrument response	12
5.5.4	Alternative determination of the overall instrument response	12
5.6	Conclusion	12
6	Test report	12
Annex A (normative)	Alternative calibration methodology	14
Annex B (informative)	Direct surface contamination evaluation: Numeric calibration examples	25
Annex C (informative)	Surface contamination evaluation for radionuclide mixtures	37
Annex D (informative)	Calibration for the indirect evaluation of surface contaminations	40
Annex E (informative)	Application of ISO 11929 for the direct evaluation of surface contaminations	44
Annex F (informative)	Application of ISO 11929 for the indirect evaluation of surface contaminations	56
Bibliography		64