

ISO 7503-3:2016-01 (E)

Measurement of radioactivity - Measurement and evaluation of surface contamination - Part 3: Apparatus calibration

Contents	Page
Foreword	iv
Introduction	v
1 Scope	1
2 Normative references	1
3 Terms, definitions, symbols, and abbreviated terms	2
3.1 Terms and definitions	2
3.2 Symbols and abbreviated terms	2
4 Surface contamination evaluation methods	3
5 Principal direct calibration methodology including summation correction	4
5.1 General	4
5.2 Calibration for radionuclides with single emission decay schemes	4
5.3 P-factor for radionuclides with uncomplex decay schemes	6
5.4 P-factors for radionuclides with complex decay schemes	7
5.5 Generic estimation of instrument response	8
5.5.1 Determination of the energy response of the instrument	8
5.5.2 Modelling of the decay paths of the radionuclide of interest	9
5.5.3 Determination of the overall instrument response	12
5.5.4 Alternative determination of the overall instrument response	12
5.6 Conclusion	12
6 Test report	12
Annex A (normative) Alternative calibration methodology	14
Annex B (informative) Direct surface contamination evaluation: Numeric calibration examples	25
Annex C (informative) Surface contamination evaluation for radionuclide mixtures	37
Annex D (informative) Calibration for the indirect evaluation of surface contaminations	40
Annex E (informative) Application of ISO 11929 for the direct evaluation of surface contaminations	44
Annex F (informative) Application of ISO 11929 for the indirect evaluation of surface contaminations	56
Bibliography	64