

# ISO/TS 11665-12:2018 (E)

## Measurement of radioactivity in the environment — Air: radon-222 — Part 12: Determination of the diffusion coefficient in waterproof materials: membrane one-side activity concentration measurement method

---

### Contents

	Foreword
	Introduction
1	Scope
2	Normative references
3	Terms, definitions and symbols
3.1	Terms and definitions
3.2	Symbols
4	Principle
5	Equipment
6	Sample preparation
6.1	General consideration
6.2	Fixing the sample in the holder
6.3	Connection of the holder (cap) with the chamber
7	Control measurements
7.1	Verification of radon-tightness
7.2	Calibration
7.3	Detector background
7.4	Instrument statistical fluctuation
8	Measurement of radon activity concentration
9	Processing and expression of the results for the sample
9.1	Determination of the radon diffusion coefficient in the sample
9.2	Characteristics of measurement limits
9.3	Estimation of confidence interval and uncertainty
9.4	Expression of the results
10	Requirements for the test
11	Influencing factors
12	Expression of the results and assessment of the standard uncertainty for the material
13	Quality management and calibration of the test device
14	Test report
14.1	The test report for material
14.2	The test report for each sample
14.3	Archived material
Annex A	(informative) Determination of the radon diffusion coefficient of the sample
A.1	Scope
A.2	Method of calculation of radon activity concentration in the source-detect chamber

- A.3**      **Example: Determination of the radon diffusion coefficient of the sample from the waterproof material (polyolefin) with a thickness of 0,60 mm**
- A.4**      **Example: the statistical uncertainty of the test results of different materials**
- A.5**      **Example: the parameters and design of the calibrated hole**

**Page count: 27**