

ISO 20042:2019 (E)

Measurement of radioactivity — Gamma-ray emitting radionuclides — Generic test method using gamma-ray spectrometry

Contents

	Foreword
	Introduction
1	Scope
2	Normative references
3	Terms and definitions
4	Symbols and units
5	Principle
5.1	General
5.2	Summing method
5.3	Fitting method
6	Validating measurements by gamma-ray spectrometry
6.1	General
6.2	Step 1: customer requirements
6.3	Step 2: technical requirements
6.4	Step 3: detailed design
6.5	Step 4: installation
6.6	Step 5: validation studies
6.7	Step 6: robustness
6.8	Step 7: operation and maintenance
7	Nuclear decay data
7.1	Recommended nuclear decay data
7.2	Selection of gamma-ray photopeaks for inclusion in spectrum analysis libraries
7.3	Decay chains
8	Detector energy and efficiency calibration
8.1	Energy calibration
8.2	Efficiency calibration
8.3	Source(s) for energy calibration
8.4	Reference source(s) for efficiency calibration
8.4.1	General
8.4.2	Reference sources for laboratory systems
8.4.3	Reference sources used with numerical methods
9	Sample container
10	Procedure
10.1	Sample measuring procedure
10.1.1	Sampling
10.1.2	Sample preparation
10.1.3	Loading the sample container
10.1.4	Recording the sample spectrum
10.2	Analysis of the spectrum
10.2.1	Procedure for laboratory-based measuring systems
10.2.2	Background corrections

- 11 Expression of results
 - 11.1 Calculation of activity and activity per kg (or m3) of sample
 - 11.2 Determination of the characteristic limits
- 12 Test report
- Annex A (informative) Quality assurance and quality control program
 - A.1 General
 - A.2 Influencing variables
 - A.3 Instrument verification
 - A.4 Method verification
 - A.5 Quality assurance plan
 - A.6 Energy calibration
 - A.7 Efficiency calibration
 - A.8 Full width half maximum
 - A.9 Background
 - A.10 Staff training and assessment
 - A.11 Documentation
- Annex B (informative) Corrections to the analysis process
 - B.1 General
 - B.2 Sample geometry
 - B.3 Composition and density correction (internal absorption)
 - B.4 Pulse pile-up and dead time
 - B.5 True coincidence summing correction
- Annex C (informative) Uncertainty budget
 - C.1 General
 - C.2 Uncertainty components
 - C.3 Implementation of uncertainty budget
- Annex D (informative) Detector types
- Annex E (informative) Example: Calculation of ¹³⁷Cs activity content and characteristic limits in an aqueous sample
 - E.1 Principle
 - E.2 Measurement
 - E.3 Calculation of activity content
 - E.4 Characteristic limits
 - E.5 Decision threshold
 - E.6 Detection limit
- Annex F (informative) Example: Simulating correction factors for sample positioning, geometry, matrix, density and true summing
 - F.1 Introduction
 - F.2 Effect of sample-to-detector distance (H1)
 - F.3 Effect of off-axis displacement (PA)
 - F.4 Effect of fill height (HS)
 - F.5 Detection efficiency for different layer of the sample
 - F.6 Effect of density (RO) and matrix (MA)
 - F.7 Effect of true coincidence summing as a function of sample to detector distance (H1)
 - F.8 Summary