

ISO 6980-3:2023-11 (E)

Nuclear energy - Reference beta-particle radiation - Part 3: Calibration of area and personal dosemeters and the determination of their response as a function of beta radiation energy and angle of incidence

Contents

	Page
Foreword	iv
Introduction	v
1 Scope	1
2 Normative references	1
3 Terms and definitions	1
4 Symbols and abbreviated terms, and reference and standard test conditions	3
5 Procedures applicable to all area and personal dosemeters	4
5.1 General principles	4
5.1.1 Selection of sources and radiation qualities	4
5.1.2 Reference absorbed dose rate	4
5.1.3 Conversion coefficients	5
5.1.4 Reference conditions and standard test conditions	5
5.1.5 Variation of influence quantities	5
5.1.6 Point of test and reference point	6
5.1.7 Axes of rotation	6
5.1.8 Condition of the dosimeter to be calibrated	6
5.1.9 Influence of photon contribution	6
5.2 Determination of calibration and correction factors	6
5.2.1 Determination of the reference dose rate by a standard instrument	6
5.2.2 Determination of reference calibration factor and correction factor for non-linear response	7
5.2.3 Determination of the correction factor for beta-particle energy and angle of incidence, k_E ,	7
6 Procedures for area dosimeters	8
6.1 General principles	8
6.2 Quantity to be measured	8
7 Procedures for personal dosimeters	8
7.1 General principles	8
7.2 Quantity to be measured	8
7.3 Experimental conditions	8
7.3.1 Use of phantoms	8
7.3.2 Geometrical considerations in divergent beams	9
7.3.3 Simultaneous irradiation of several dosimeters	9
8 Uncertainties	10
9 Reporting of results according to ISO 17025	10
Annex A (normative) Reference conditions and standard test conditions	11
Annex B (informative) Conversion coefficients for some beta reference radiation fields	13
Bibliography	19