

ISO 4037-4:2004-10 (E)

X and gamma reference radiation for calibrating dosimeters and doserate meters and for determining their response as a function of photon energy - Part 4: Calibration of area and personal dosimeters in low energy X reference radiation fields

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	2
4	Symbols (and abbreviated terms)	2
5	General procedures for calibrating and determining response	4
6	Characterisation and production of low energy X-ray reference radiations	4
6.1	General	4
6.2	Tube potential	4
6.3	Field uniformity and scattered radiation	5
6.4	Spectral fluence and conversion coefficients	5
7	Dosimetry of low energy reference radiations	6
7.1	General	6
7.2	Operation of the standard instruments	6
7.2.1	Instruments for the measurement of air kerma	6
7.2.2	Instruments for the measurement of the dose-equivalent quantities defined in ICRU 51	6
8	Calibration and determination of the response as a function of photon energy and angle of radiation incidence	6
8.1	General	6
8.2	Selection of calibration method	7
8.3	Calibration by using reference instruments for K_{α}	7
8.3.1	General	7
8.3.2	Conventionally true value of the measurand air kerma	7
8.3.3	Conventionally true value of the measurands dose-equivalent quantities $H_p(0,07)$ and $H(0,07)$	8
8.3.4	Conventionally true value of the measurands dose-equivalent quantities $H_p(10)$ and $H^*(10)$	8
8.3.5	Performing the calibration	10
8.4	Calibration by using reference instruments which measure the ICRU dose-equivalent quantities	10
8.4.1	General	10
8.4.2	Conventionally true value of the measurands dose-equivalent quantities $H_p(10)$ and $H^*(10)$	10
8.4.3	Performing the calibration	12
8.5	Statement of uncertainty	12
Annex A (normative)	Correction for air density	13
Annex B (informative)	Measurement of pulse height spectra	17
Bibliography		19