

ISO 25337:2010-03 (E)

Plastics - Production quality control - Statistical method for using single measurements

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Precision of test methods	2
5	Single measurements for production quality control purposes	3
5.1	General	3
5.2	Variability of the production process and test method	3
5.3	Within-laboratory reproducibility	4
5.4	Calculation of sRLab from a within-laboratory reproducibility investigation	4
5.5	Interpretation of single-measurement data for production quality control purposes	5
6	Procedure	8
Annex A (informative)	Example of the calculation of sRLab from a within-laboratory reproducibility investigation	9
Annex B (informative)	Examples of the effect on production limits of making duplicate and triplicate measurements as opposed to single measurements	11
Annex C (normative)	Reducing the probability of incorrectly accepting a nonconforming product ...	15
Bibliography		17