

# ISO 25337:2010-03 (E)

## Plastics - Production quality control - Statistical method for using single measurements

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
1	Scope .....	1
2	Normative references .....	1
3	Terms and definitions .....	1
4	Precision of test methods .....	2
5	Single measurements for production quality control purposes .....	3
5.1	General .....	3
5.2	Variability of the production process and test method .....	3
5.3	Within-laboratory reproducibility .....	4
5.4	Calculation of sRLab from a within-laboratory reproducibility investigation .....	4
5.5	Interpretation of single-measurement data for production quality control purposes .....	5
6	Procedure .....	8
Annex A (informative)	Example of the calculation of sRLab from a within-laboratory reproducibility investigation .....	9
Annex B (informative)	Examples of the effect on production limits of making duplicate and triplicate measurements as opposed to single measurements .....	11
Annex C (normative)	Reducing the probability of incorrectly accepting a nonconforming product ...	15
Bibliography .....		17