

ISO 11357-2:2013-05 (E)

Plastics - Differential scanning calorimetry (DSC) - Part 2: Determination of glass transition temperature and glass transition step height

Contents		Page
Foreword		iv
1 Scope		1
2 Normative references		1
3 Terms and definitions		1
4 Principle		2
5 Apparatus and materials		2
6 Test specimens		2
7 Test conditions and specimen conditioning		2
8 Calibration		2
9 Procedure		2
9.1 Setting up the apparatus		2
9.2 Loading the test specimen into the crucible		2
9.3 Insertion of crucibles		2
9.4 Temperature scan		2
10 Expression of results		3
10.1 Determination of glass transition temperatures		3
10.2 Determination of glass transition step height		5
11 Precision		5
12 Test report		5
Bibliography		6