

# DIN EN 13999-1:2014-03 (E)

## Adhesives - Short term method for measuring the emission properties of low-solvent or solvent-free adhesives after application - Part 1: General procedure

---

<b>Contents</b>		<b>Page</b>
Foreword .....		3
Introduction .....		5
1	Scope .....	6
2	Normative references .....	6
3	Terms and definitions .....	6
4	Principle .....	6
5	Apparatus .....	7
5.1	General .....	7
5.2	Support .....	7
5.3	Adhesive coating device .....	7
5.4	Emission test chamber .....	7
5.5	Air supply and mixing facilities .....	8
5.6	Air sampling devices .....	9
5.7	Devices for desorption and analysis .....	9
6	Adhesive sample .....	9
6.1	General .....	9
6.2	Pre-conditioning .....	9
6.3	Preparation of a test specimen .....	9
7	Procedure .....	10
7.1	Number of determinations .....	10
7.2	Preconditioning of the test chamber .....	10
7.3	Operation of the test chamber .....	10
7.4	Starting of the test .....	10
7.5	Sampling and analysis of emitted substances .....	10
8	Expression of results .....	11
8.1	Calculations .....	11
8.2	Carcinogenic and sensitizing compounds concentration .....	11
8.3	Volatile organic compounds .....	11
8.3.1	General .....	11
8.3.2	Determination of the specific emission rate at the sampling times .....	11
8.3.3	Determination of the empirical parameters a and b .....	12
9	Test report .....	13
Annex A (normative) Carcinogenic and sensitizing substances .....		14
Bibliography .....		15