

# ISO 1183-3:1999-09 (E)

## Plastics - Methods for determining the density of non-cellular plastics - Part 3: Gas pyknometer method

---

<b>Contents</b>		<b>Page</b>
1	Scope .....	1
2	Terms, definitions, symbols, units and abbreviated terms .....	1
3	Principle .....	2
4	Apparatus and materials .....	3
5	Test specimens .....	3
6	Calibration .....	3
7	Procedure and calculation .....	4
8	Precision .....	4
9	Test report .....	4
Annex A (informative) Two-chamber pressure-measuring pyknometer .....		6