

# ISO 1183-3:1999-09 (E)

## Plastics - Methods for determining the density of non-cellular plastics - Part 3: Gas pyknometer method

---

| <b>Contents</b>   |  | <b>Page</b> |
|---|--|-------------|
| 1   | Scope .....  | 1           |
| 2   | Terms, definitions, symbols, units and abbreviated terms ..... | 1           |
| 3   | Principle .....  | 2           |
| 4   | Apparatus and materials .....                                  | 3           |
| 5   | Test specimens .....   | 3           |
| 6   | Calibration .....  | 3           |
| 7   | Procedure and calculation .....                                | 4           |
| 8   | Precision .....  | 4           |
| 9   | Test report .....  | 4           |
| Annex A (informative) Two-chamber pressure-measuring pyknometer ..... |  | 6           |