

ISO/TS 19022:2016-02 (E)

Plastics - Method of controlled acceleration of laboratory weathering by increased irradiance

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Symbols and abbreviated terms	2
5	Principle	2
6	Apparatus	2
6.1	General	2
6.2	Test chamber	2
6.3	Laboratory radiation source	3
6.3.1	General	3
6.3.2	Spectral irradiance	3
6.3.3	Irradiance uniformity	3
6.4	Radiometer	4
6.5	Test chamber temperature and relative humidity	4
6.6	Black-standard/black-panel thermometer	4
6.7	Wetting and humidity-control equipment	4
6.7.1	General	4
6.7.2	Relative-humidity control equipment	4
6.7.3	Spray system	4
6.8	Specimen holders	4
6.9	Apparatus to assess changes in properties	5
7	Test specimens	5
8	Test method	5
9	Exposure conditions	6
9.1	Radiation	6
9.2	Temperature	6
9.2.1	Black-standard and black-panel temperature	6
9.2.2	Chamber air temperature	6
9.2.3	Specimen surface temperature	6
9.3	Humidity of chamber air	7
9.3.1	Relative humidity of chamber air	7
9.3.2	Spray cycle	7
10	Procedure	7
10.1	General	7
10.2	Mounting the test specimens	7
10.3	Exposure	7
10.4	Measurement of radiant exposure	8
10.5	Determination of changes in properties after exposure	8

11	Test report	8
	Annex A (informative) Principle of reciprocity	9
	Bibliography	10