

ISO 11357-1:2016-09 (E)

Plastics - Differential scanning calorimetry (DSC) - Part 1: General principles

Contents		Page
Foreword		v
Introduction		vi
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Basic principles	8
4.1	General	8
4.2	Heat-flux DSC	8
4.3	Power-compensation DSC	8
5	Apparatus and materials	9
6	Specimen	10
7	Test conditions and specimen conditioning	11
7.1	Test conditions	11
7.2	Conditioning of specimens	11
8	Calibration	11
8.1	General	11
8.2	Calibration materials	12
8.3	Temperature calibration	12
8.3.1	General	12
8.3.2	Procedure	12
8.3.3	Accuracy of calibration	13
8.4	Heat calibration	13
8.4.1	General	13
8.4.2	Procedure	14
8.4.3	Accuracy of calibration	14
8.5	Heat flow rate calibration	15
8.5.1	General	15
8.5.2	Procedure	15
9	Procedure	17
9.1	Setting up the apparatus	17
9.1.1	Switching on	17
9.1.2	Purge gas	17
9.1.3	Experimental conditions	17
9.1.4	Baseline determination	17
9.2	Loading the specimen into the crucible	17
9.2.1	General	17
9.2.2	Selection of crucibles	18
9.2.3	Weighing the specimen crucible	18
9.2.4	Loading the specimen	18
9.2.5	Determination of the mass of the specimen	18
9.3	Insertion of crucibles into the instrument	18
9.4	Performing measurements	18

9.4.1	General	18
9.4.2	Scanning mode	18
9.4.3	Isothermal mode	19
9.5	Post-run checks	20
9.5.1	Check for loss in mass	20
9.5.2	Inspection of specimens	20
9.5.3	Checking of crucibles and crucible holder	20
10	Test report	20
Annex A (normative) Extended, high-precision, temperature calibration[12]		22
Annex B (normative) Extended, high-precision, heat calibration		24
Annex C (informative) Recommended calibration materials		26
Annex D (informative) Interaction of calibration materials with different crucible materials		29
Annex E (informative) General recommendations		31
Bibliography		33