

# DIN EN ISO 5659-2:2017-11 (E)

## Plastics - Smoke generation - Part 2: Determination of optical density by a single-chamber test (ISO 5659-2:2017)

---

<b>Contents</b>		Page
<b>European foreword</b>		4
<b>Foreword</b>		5
<b>Introduction</b>		6
<b>1 Scope</b>		7
<b>2 Normative references</b>		7
<b>3 Terms and definitions</b>		7
<b>4 Principles of the test</b>		9
<b>5 Suitability of a material or product for testing</b>		9
5.1	Material or product geometry	9
5.2	Surface characteristics	9
5.3	Asymmetrical products	9
<b>6 Specimen construction and preparation</b>		10
6.1	Number of specimens	10
6.2	Size of specimens	10
6.3	Specimen preparation	10
6.4	Conditioning	11
6.5	Wrapping of specimens	11
<b>7 Apparatus and ancillary equipment</b>		11
7.1	General	11
7.2	Test chamber	12
7.2.1	Construction	12
7.2.2	Chamber pressure control facilities	12
7.2.3	Chamber wall temperature	15
7.3	Specimen support and heating arrangements	16
7.3.1	Radiator cone	16
7.3.2	Framework for support of the radiator cone, specimen holder and heat flux meter	16
7.3.3	Radiator shield	19
7.3.4	Heat flux meter	19
7.3.5	Specimen holder	20
7.3.6	Pilot burner	20
7.4	Gas supply	21
7.5	Photometric system	21
7.5.1	General	21
7.5.2	Light source	21
7.5.3	Photo detector	21
7.5.4	Additional equipment	22
7.6	Chamber leakage	22
7.7	Cleaning materials	24
7.8	Ancillary equipment	24
7.8.1	Balance	24
7.8.2	Timing device	24
7.8.3	Linear measuring devices	24
7.8.4	Auxiliary heater	24
7.8.5	Protective equipment	24
7.8.6	Recorder	24
7.8.7	Water-circulating device	24
<b>8 Test environment</b>		

<b>9</b>	<b>Setting-up and calibration procedures</b>	<b>25</b>
9.1	General	25
9.2	Alignment of photometric system	25
	9.2.1 General	25
	9.2.2 Beam collimation	25
	9.2.3 Beam focusing	25
9.3	Selection of compensating filter(s)	25
9.4	Linearity check	26
9.5	Calibration of range-extension filter	26
9.6	Chamber leakage rate test	27
9.7	Burner calibration	27
9.8	Radiator cone calibration	27
9.9	Cleaning	28
9.10	Frequency of checking and calibrating procedure	28
<b>10</b>	<b>Test procedure</b>	<b>28</b>
10.1	General	28
10.2	Preparation of test chamber	28
10.3	Tests with pilot flame	29
10.4	Preparation of the photometric system	29
10.5	Loading the specimen	29
10.6	Recording of light transmission	29
10.7	Observations	30
10.8	Termination of test	30
10.9	Testing in different modes	31
<b>11</b>	<b>Expression of results</b>	<b>31</b>
11.1	Specific optical density, $D_s$	31
11.2	Clear-beam correction factor, $D_c$	32
<b>12</b>	<b>Precision</b>	<b>32</b>
<b>13</b>	<b>Test report</b>	<b>32</b>
<b>Annex A (normative) Calibration of heat flux meter</b>		<b>34</b>
<b>Annex B (informative) Variability in the specific optical density of smoke measured in the single-chamber test</b>		<b>35</b>
<b>Annex C (informative) Determination of mass optical density</b>		<b>37</b>
<b>Annex D (informative) Precision data from tests on intumescent materials</b>		<b>42</b>
<b>Annex E (informative) Guidance on optical density testing</b>		<b>46</b>
<b>Annex F (informative) Specific sample preparation</b>		<b>52</b>
<b>Bibliography</b>		<b>55</b>