

# ISO 23976:2021-02 (E)

## Plastics - Fast differential scanning calorimetry (FSC) - Chip calorimetry

---

<b>Contents</b>		<b>Page</b>
Foreword		v
Introduction		vi
<b>1</b>	<b>Scope</b>	<b>1</b>
<b>2</b>	<b>Normative references</b>	<b>2</b>
<b>3</b>	<b>Terms and definitions</b>	<b>2</b>
<b>4</b>	<b>Principle</b>	<b>3</b>
<b>5</b>	<b>Apparatus</b>	<b>4</b>
5.1	Chip calorimeter	4
5.2	Microscope	5
5.3	Tools for sample preparation	5
5.4	Calibration materials	5
5.5	Measuring atmosphere	5
<b>6</b>	<b>Specimens</b>	<b>5</b>
<b>7</b>	<b>Test conditions and specimen conditioning</b>	<b>6</b>
7.1	Test conditions	6
7.2	Conditioning of specimens	6
<b>8</b>	<b>Calibration</b>	<b>6</b>
8.1	Chip calorimeter performance	6
8.2	Temperature calibration <sup>[14],[17]</sup>	8
8.2.1	General	8
8.2.2	Correction for thermal lag due to scan rate	9
8.2.3	Correction for thermal lag due to sample mass	10
8.2.4	Correction of measured temperature extrapolated to zero heating rate	10
8.3	Symmetry of temperature calibration <sup>[14],[17],[21]</sup>	12
8.3.1	General	12
8.3.2	Procedure	12
8.4	Calibration of heat and heat flow rate	13
<b>9</b>	<b>Specimen measurement procedure</b>	<b>14</b>
9.1	Preparation of apparatus	14
9.1.1	Starting the instrument	14
9.1.2	Purge gas	14
9.1.3	Preparation of sensor	14
9.1.4	Blank correction for heat loss <sup>[23]</sup>	14
9.2	Placement of specimens on the sensor	15
9.3	Performance of measurements	16
9.3.1	General	16
9.3.2	Running the instrument	17
9.3.3	Reuse of chip sensor	17
9.3.4	Evaluation of results	17
<b>10</b>	<b>Investigation of physical-chemical effects</b>	<b>17</b>
10.1	General	17
10.2	First Order phase transitions	17
10.3	Chemical reactions	17
10.4	Glass transitions	18

<b>11</b>	<b>Determination of heat capacity</b> <sup>[24]</sup> .....	<b>18</b>
<b>12</b>	<b>Determination of specimen mass</b> <sup>[14],[23]</sup> .....	<b>20</b>
12.1	General .....	20
12.2	Determination of specimen mass based on specific heat capacity of material .....	21
12.3	Determination of specimen mass based on specific heat capacity change at glass transition .....	21
12.4	Determination of specimen mass based on specific enthalpy of fusion .....	22
12.5	Determination of specimen mass based on specimen dimensions and density .....	23
12.6	Use of FSC reference specimens .....	23
12.7	Criteria for selection of correct specimen mass .....	23
12.7.1	High specimen mass .....	23
12.7.2	Low specimen mass .....	24
<b>13</b>	<b>Precision and bias</b> .....	<b>24</b>
<b>14</b>	<b>Test report</b> .....	<b>25</b>
	<b>Bibliography</b> .....	<b>26</b>