

# ISO 4765:2022-04 (E)

## Chemically- induced ultra-weak photon emission (UPE) - Measurement as an analysis method of degradation of polymeric material

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
1	Scope .....	1
2	Normative references .....	1
3	Terms and definitions .....	1
4	Measurement principle and its limitations .....	2
5	Sample .....	2
6	UPE measuring apparatus .....	3
6.1	Composition of UPE apparatus body .....	3
6.2	Composition of sample chamber .....	3
6.3	Installation environment for UPE apparatus .....	4
6.4	Sensitivity check .....	4
7	Measurement method .....	5
7.1	UPE apparatus preparation .....	5
7.2	Confirmation of normal operation of UPE apparatus .....	5
7.3	Measurement procedure .....	5
7.3.1	Setting of measurement condition .....	5
7.3.2	Measurement of background .....	6
7.3.3	Sample measurement .....	6
8	Display of measurement results .....	7
8.1	General .....	7
8.2	Measurement in inert gas atmosphere .....	7
8.3	Measurement in oxidation accelerating atmosphere .....	8
9	Test report .....	10
Annex A (informative) Detection of oxidation deterioration by UPE measurement .....		11
Annex B (informative) Examples of time courses of UPE of thermally oxidized polypropylene (PP) for isothermal and non-isothermal measurement .....		16
Annex C (informative) Example of measurements of oxidation deterioration degree of thermally oxidized polyethylene (PE) .....		18
Annex D (informative) Example evaluation of oxidation induction time (OIT) .....		20
Annex E (informative) Example of UPE of PP oxidized by accelerated weathering test .....		22
Bibliography .....		26