

ISO 4892-4:2024-12 (E)

Plastics - Methods of exposure to laboratory light sources - Part 4: Open-flame carbon-arc lamps

Contents		Page
Foreword		iv
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Principle	1
5	Apparatus	2
5.1	Laboratory light source	2
5.1.1	General	2
5.1.2	Spectral irradiance of open-flame carbon-arc lamps with daylight filters (type 1)	2
5.1.3	Spectral irradiance of open-flame carbon-arc lamps with window-glass filters (type 2)	3
5.1.4	Spectral irradiance of open-flame carbon-arc lamps with extended-UV filters (type 3)	4
5.1.5	Typical spectral irradiance:	4
5.1.6	Factors that can affect the spectral power distribution of open-flame carbon- arc lamps	6
5.2	Test chamber	7
5.3	Radiometer	7
5.4	Thermometer	7
5.5	Moisture	7
5.5.1	General	7
5.5.2	Relative-humidity control equipment	7
5.5.3	Spray system	7
5.6	Specimen holders	7
5.7	Apparatus to assess changes in properties	8
6	Test specimens	8
7	Test conditions	8
7.1	Temperature	8
7.1.1	Black-standard/black-panel temperature	8
7.1.2	Chamber air temperature	8
7.2	Relative humidity of air	8
7.3	Spray cycle	8
7.4	Cycles with dark periods	9
8	Procedure	9
8.1	Mounting the test specimens	9
8.2	Exposure	9
8.3	Measurement of radiant exposure	9
8.4	Determination of changes in properties after exposure	9
9	Exposure report	9
Bibliography		10