

# ISO 4892-4:2024-12 (E)

## Plastics - Methods of exposure to laboratory light sources - Part 4: Open-flame carbon-arc lamps

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Terms and definitions .....</b>	<b>1</b>
<b>4</b>	<b>Principle .....</b>	<b>1</b>
<b>5</b>	<b>Apparatus .....</b>	<b>2</b>
5.1	Laboratory light source .....	2
5.1.1	General .....	2
5.1.2	Spectral irradiance of open-flame carbon-arc lamps with daylight filters (type 1) .....	2
5.1.3	Spectral irradiance of open-flame carbon-arc lamps with window-glass filters (type 2) .....	3
5.1.4	Spectral irradiance of open-flame carbon-arc lamps with extended-UV filters (type 3) .....	4
5.1.5	Typical spectral irradiance: .....	4
5.1.6	Factors that can affect the spectral power distribution of open-flame carbon- arc lamps ....	6
5.2	Test chamber .....	7
5.3	Radiometer .....	7
5.4	Thermometer .....	7
5.5	Moisture .....	7
5.5.1	General .....	7
5.5.2	Relative-humidity control equipment .....	7
5.5.3	Spray system .....	7
5.6	Specimen holders .....	7
5.7	Apparatus to assess changes in properties .....	8
<b>6</b>	<b>Test specimens .....</b>	<b>8</b>
<b>7</b>	<b>Test conditions .....</b>	<b>8</b>
7.1	Temperature .....	8
7.1.1	Black-standard/black-panel temperature .....	8
7.1.2	Chamber air temperature .....	8
7.2	Relative humidity of air .....	8
7.3	Spray cycle .....	8
7.4	Cycles with dark periods .....	9
<b>8</b>	<b>Procedure .....</b>	<b>9</b>
8.1	Mounting the test specimens .....	9
8.2	Exposure .....	9
8.3	Measurement of radiant exposure .....	9
8.4	Determination of changes in properties after exposure .....	9
<b>9</b>	<b>Exposure report .....</b>	<b>9</b>
Bibliography .....		10